AUG 24 2009 Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-015-01646 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE \square 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A EMPIRE ABO UNIT 'H' DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 9. OGRID Number 2. Name of Operator 00778 BP America Production Company 10. Pool name or Wildcat 3. Address of Operator P.O. Box 1089 Eunice NM 88231 EMPIRE ABO 4. Well Location 660 feet from the line and feet from the line Unit Letter Township **17**S Range 28E **NMPM** County FIDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3681' RDB Pit or Below-grade Tank Application or Closure __ Distance from nearest fresh water well ______ Distance from nearest surface water _ Pit type ____ ____ Depth to Groundwater ___ Pit Liner Thickness: .. Below-Grade Tank: Volume_____bbls; Construction Material . 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON [REMEDIAL WORK ALTERING CASING ... PERFORM REMEDIAL WORK **CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND** X **TEMPORARILY ABANDON ABANDONMENT** CASING TEST AND **PULL OR ALTER CASING MULTIPLE CEMENT JOB** COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8/13/09: LOAD TEST TBG 600 PSI (OK). FUMPED 40 BBLS DN BACKSIDE WELL ON VAC. RU PU. POOH W/ RODS & PUMP. 8/14/09: PUMPED 40 BBLS FRESHWATER, WELL ON VAC, ND WH, NU BOP, POOH W/ TBG & TAC. RIH W/ 40 JT KILLSTRING. 8/17/09: PUMP 20 BBLS FRESHWATER, POOH W/ KILLSTRING, RIH W/ 5.5" CIBP SET @5740'. LOAD WELLBORE W/ FRESHWATER 130 BBLS. TEST CSG & CIBP TO 500 PSI (OK). M&P 25 SKS 15.1 CLASS (C) OMT. DISPLACE W/ 20.5 BBLS, POOH L/D 10 JTS TBG. CIRC WELL W/ 125 BBLS 9.5 PPG. SALIWATER GEL. POOH TO 3512' M&P 25 SKS 14.9 PPG CLASS (C) OMT GLORIETA PLUG W.O.C. POOH. RIH TO 2000'. Continued on page 2. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines _____, a general permit ______ or an (attached) alternative OCD-approved plan _____ SIGNATURE & TITLE Area Operations Team Lead DATE

E-mail address:

Type or print name Barry C. Price

Conditions of Approval, if any:

For State Use Only

APPROVED BY /

Approved for plugging of well bore only.

Liability under bond is retained pending receipt

of C.103 (Subsequent Report of Well Plugging)

which may be found at OCD Web Page under

Forms, www.cmnrd.state.nm.us/ocd.

Telephone No. 575-394-1648

barry.price@bp.com

Form C-103 Empire Abo Unit H-22 30-015-01646 Continued from Page 1

8/19/09: RELEASE PKR. CIR WELL 3BPM 300 PSI BROKE CIRC. 5.5" X8 5/8" CSG. CLEANED UP GOOD 95 BBLS RESET PKR. TEST BACKSIDE 500 PSI (OK) RELEASE PKR. POOH L/D PKR. N/D BOP N/U BONNET. M&P 120 SKS. CLASS (C) 14.9 PPG. CMT. F- 450' T-SURFACE 250PSI SQZ. SHUT IN ON SURFACE. ALL WELL WORK APPROVED BY PHIL HAWKINS, NMOCD.

8/20/09: DIG OUT AROUND WELLHEAD. CUT OFF ALL ANCHORS AND WELL HEAD, WELD IN PLATE, 1" NIPPLE & VALVE, DRY HOLE MARKER, BACKFILL AND LEVEL LOCATION.