				I		
Submit 3 Copies To Appropriate District State of New Mexico			1		Form C-103	
Office District I	Energy, Minerals and Natural Resources			June 19, 2008		
1625 N. French Dr., Hobbs, NM 88240	,			WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-29555		
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE FEE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, INIVI 67303			6. State Oil & Gas Lease No.		
87505						
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C. 1911 FOR SUCH PROPOSALS.)				MARATH	ON 25 STATE	
PROPOSALS.)	BECHNED					
	Gas Well Other			8. Well Number #6		
2. Name of Operator		DEC -4 2009		9. OGRID Number 255333		
LIME ROCK RESOURCES A, L.P.			DEC 42003		1	
3. Address of Operator		NMOCD ARTESIA		10. Pool name or Wildcat: (51300)		
c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401				Red Lake, Queen-Grayburg-San Andres		
4. Well Location						
Unit Letter E: 1650 feet from the NORTH line and 990 feet from the WEST line						
Section 25	Township	17-S	Range 28-E		Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
3684' GL						
マル / No. 2 A Min 2 A						
12 Charle Appropriate Roy to Indicate Nature of Notice Depart or Other Date						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING						
TEMPORARILY ABANDON						T T
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						
DOWNHOLE COMMINGLE						
				1		
OTHER: Perf & Stimulate More San And	ires	\boxtimes	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
Lime Rock plans a same zone workover as follows: TOH w/rods, pump, & tbg. Set a RBP @ 2770 (above existing SA perfs @ 2802'-						
3392'). PT 5-1/2" csg to 500 psi. Perf additional SA @ about 2670'-2780'. Breakdown perfs w/ about 3500 gal 15% NEFE acid & frac						
w/about 65,000# 16/30 & 25,000# 12/20 sand in 25# X-linked gel. CO after frac & retrieve RBP @ 2770'. CO to PBTD3449'. Run tbg						
& land @ about 3352'. Run pump, & rods & initiate producing load water.						
				1		
Spud Date: 3/12/98	D	rilling Rig	Release Date:	3/21/98		
I hereby certify that the information above				and belief.		
	1		, ,	i		
SIGNATURE White Type	•					
• •	' <u>un</u> titi	_E_Petrole	eum Engineer - Age	<u>nt </u>	DATE12/3/0	9
				1		
Type or print name Mike Pippin		E <u>Petrole</u> l address:		1	DATE 12/3/0 PHONE: 505-3	
Type or print name Mike Pippin For State Use Only				1		
For State Use Only	E-mai	l address:		1	PHONE: _505-3	27-4573
APPROVED BY:		l address:		1		27-4573
For State Use Only	E-mai	l address:		1	PHONE: _505-3	27-4573