

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB NO 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		7. If Unit or CA/Agreement, Name and/or No
2 Name of Operator ENERVEST OPERATING, L.L.C.		8 Well Name and No WLHU GAS UNIT #006
3a Address 1001 FANNIN ST., STE. 800, HOUSTON, TEXAS 77002		9 API Well No 30-015-03392
3b Phone No (include area code) (713) 659-3500		10 Field and Pool, or Exploratory Area LOCO HILLS QUEEN-GB-SA
4 Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT LETTER N 330' FSL & 2,310' FWL SEC. 11, T-18N, R-29E		11. County or Parish, State EDDY COUNTY NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

11/13-22/09: RE-ENTER PLUGGED WELL X DRILL OUT CMT. PLUGS X OLD WELLBORE TO 3,000'.
11/23/09: MIX X PUMP A 40 SX. CMT. PLUG @ 3,000'; WOC X TAG CMT. PLUG @ 2,984'; MIX X PUMP A 40 SX. CMT. PLUG @ 2,984'; WOC X TAG TOP OF CMT. PLUG @ 2,715'; CIRC. WELL W/ FXA MUD.
11/24/09: MIX X PUMP A 60 SX. CMT. PLUG @ 2,170'; WOC X TAG TOP OF CMT. PLUG @ 2,053'.
11/25/09: MIX X PUMP A 40 SX. CMT. PLUG @ 985'; WOC - DID NOT TAG CMT. PLUG; MIX X PUMP A 2ND 40 SX. CMT. PLUG @ 985'; WOC - DID NOT TAG CMT. PLUG; MIX X PUMP A 3RD 40 SX. CMT. PLUG @ 985'; WOC.
11/30/09: TAG TOP OF CMT. PLUG @ 916'; MIX X PUMP A 40 SX. CMT. PLUG @ 916'; WOC X TAG CMT. PLUG @ 916'; PUMP 5 SXS. CEDAR FIBER X MIX X PUMP A 60 SX. CMT. PLUG @ 916'; WOC.
12/02/09: TAG TOP OF CMT. PLUG @ 886'; MIX X PUMP A 50 SX. CMT. X 1 SX. CACL PLUG @ 886'; WOC X TAG TOP OF CMT. PLUG @ 874' - SHERYL W/ BLM OK'D TAG; MIX X PUMP A 75 SX. CMT. X 1 SX. CACL PLUG @ 450'; TAG CMT. PLUG @ 220'.
12/03/09: PERF. X SQZ. A 30 SX. CMT. PLUG @ 220'; WOC - DID NOT TAG CMT. PLUG; MIX X SQZ. A 50 SX. CMT. X 2 SXS. CACL PLUG @ 220'; WOC X TAG TOP OF CMT. PLUG @ 207'.
12/04/09: PUMP 10 SXS. CEDAR FIBER X MIX X PUMP A 50 SX. CMT. PLUG @ 207'; WOC X TAG TOP OF CMT. PLUG @ 147'; PERF. X SQZ. A 5 SX. CEDAR FIBER X 100 SX. CMT. PLUG @ 130'; WOC X TAG CMT. @ 20'.
12/05/09: MIX X PUMP A 10 SX. CMT. PLUG @ 20'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) DAVID A. EYLER		Title AGENT	WELL PLUGGED X ABANDONED 12/05/09.
Date 12/08/09		ACCEPTED FOR RECORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.		Title Office	Date DEC 29 2009
BUREAU OF LAND MANAGEMENT ARTESIA FIELD OFFICE			
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.			