

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No 1004-0137
Expires July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other instructions on page 2**

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator

Seely Oil Company

3a Address

615 W. 10th St. Ft Worth, TX 76102

3b Phone No (include area code)

817-332-1377

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980 FEL
B-35-T17S-R30E

5 Lease Serial No

NM-0384576

6 If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No

Stevens Federal

8 Well Name and No

2

9 API Well No

30-015-21309

10 Field and Pool, or Exploratory Area

Grayburg-Jackson

11 County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10/28/09 MIRU. POH & lay down rods and pump. MI pit and cementing equipment. 10/29/09 dig out cellar. 4 1/2 csg. parted. Strip off head. Weld bell nipple on. NU BOP. Work tbg. free. POH w/ 3280' tbg. lay down 6 jts. RIH w/ 3100' tbg. Pumped mud laden fluid. No circulation. Pumped 1 bag of LCM. Spot 25 sx class C cement. Pulled out of cement. SDFN. 10/30/09 RIH w/ tbg. No Tag. Load hole w/ 60 bbls of mud laden fluid. Spot 25 sx class C cement. Pulled out of cement. WOC. Tagged plug @ 2943'. Spot 20 sx class C cement @ 2943'. Pulled out of cement. SDFN. 11/02/09 Tbg. stuck. RIH w/ wire line. Tag @ 1628'. RIH w/ tbg. cutter. Cut tbg @ 1487'. could not pull. RIH w/ string shot @ 1528'. Tried back off tbg. Backed off @ 785'. RIH w. tbg and screwed on. RIH w/ string shot @ 1597'. could not back off. SDFN. 11/03/09 RIH w/ tbg. cutter to 1600'. Load hole. POH w/ 1600' tbg. lay down. RIH w/ tbg. & packer, set @ 1000'. Pressure up to 500 psi. Held for 15 minutes. Perf. csg @ 1540'. Sqz 75 sx class C cement. WOC one hour. Well started flowing out of casing. released packer and pulled up to 150'. Set packer. Put pressure on plug. POH. Well leaking from around surface. Dig out cellar. Find hole in 8 5/8. 11/04/09 RIH and tag plug @ 754'. Well still flowing. Lay down tbg and tbg in derrick. ND BOP. RIH w/ 4 1/2 casing cutter. Cut csg. @ 687'. Lay down csg. Rigged down moved rig off. Stand by for backhoe and welder to repair surface csg. 11/05/09 Stand by while repairing 8 5/8 csg. Rig up. NU well head and BOP. RIH w/ mule shoe on tbg. to 800'. Spot 35 sx class C cement. SDFN. 11/06/09 RIH and tagged plug @ 770'. Lay down one jt. Spot 50 sx class C cement @ 740'. POH w/ tbg. WOC. RIH w/ tbg. tagged @ 693'. Cement green. POH w/ tbg. 11/09/09 RIH and tag plug @ 663'. Spot 60 sx. class C cement @ 663'. POH. WOC. SDFN. 11/10/09 Tag plug @ 643'. Spot 60 sx class C cement @ 643'. POH. WOC. Tag plug @ 598'. Spot 60 sx. @ 598'. POH. SDFN. 11/11/09 RIH w/ tbg. Tag plug @ 578'. Spot 25 sx class C cement @ 578'. POH. WOC. Tag plug @ 568'. Spot 100 sx class C cement. POH SDFN.

14 I hereby certify that the foregoing is true and correct /

Name (Printed Typed)

Title

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

Signature

on page 2

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

DEC 29 2009

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE – Other instructions on page 2

1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2 Name of Operator

Seely Oil Company

3a Address

615 W. 10th St. Ft Worth, TX 76102

3b Phone No (include area code)

817-332-1377

4 Location of Well (Footage, Sec, T, R, M, or Survey Description)

**660' FNL & 1980 FEL
B-35-T17S-R30E**

5 Lease Serial No

NM-0384576

6 If Indian, Allottee or Tribe Name

7 If Unit or CA/Agreement, Name and/or No

Stevens Federal

8 Well Name and No

2

9 API Well No

30-015-21309

10 Field and Pool, or Exploratory Area

Grayburg-Jackson

11 County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

11/12/09 RIH and tag plug @ 513'. Spot 100 sx class C cement. POH. WOC. Tag plug @ 93'. POH and ND. BOP. RIH to 90'. Circulate 30 sx class C cement to surface. rig down move off. 11/16/09 Move in welder and backhoe. cut off well head and weld on Dry Hole Marker. Back fill cellar. Cut off dead men. clean location move off.

14 I hereby certify that the foregoing is true and correct.)

Name (Printed/Typed)

David L. Henderson

Title

Exec. V-P

Signature

David L. Henderson

Date

12/4/09

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)