

RECEIVED

Submit 3 Copies  
to Appropriate  
District Office

MAR 15 2010

State of New Mexico  
Energy, Minerals and Natural Resources Department

TRAVIS

Form C-103  
Revised 1-1-89

MOOD ARTESIA

## OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 874102040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-015-30247
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	William Lightfoot 20 State DHC No. 2788
8. Well No.	1
9. Pool name or Wildcat	Winchester: UpPennW /Wildcat: Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GL 3468 KB 3486

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Marathon Oil Company	3. Address of Operator P.O. Box 2490 Hobbs, NM 88240	4. Well Location Unit Letter M : 810 Feet From The South Line and 660 Feet From The West Line Section 20 Township 19-S Range 28-E NMPM Eddy County
---	---	---	--

## 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: RE Wolfcamp & DHC w/Winchester: Up Penn W. ☒

## 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/7 RU pulling unit. ND wellhead. NU BOP. Rel pkr. TOOH w/2 7/8" tbg. RIH w/RBP & pkr. Set RBP at 9550', pkr at 9520'. Test RBP, OK. Rel pkr.  
 4/12 Spot 250 gals 15% acid. TOH w/pkr. Perf Wolfcamp 8814-8824', w/4 SPF. 40 holes. RIH w/pkr. set at 8528'. Acidize w/1000 gals 15% acid. Swab. Reset pkr at 8558'. Re-acidize w/3000 gals. Swab.  
 4/19 Rel pkr, rel RBP. POOH w/both. RIH w/2 7/8" tbg.  
 4/20 ND BOP. NU wellhead. Hot water tbg. RIH w/pump & rods. Load & test, OK  
 4/21 RD pulling unit.

TAC at 8684'  
 SN at 9741'  
 Btm of tbg 9772'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/18/00  
 TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: