N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Ayenue

Rm

Form 3160-5 (August 2007) UNITED STATES Artesia, NM 88210
DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

5. Lease Serial No. NM - 8431 **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or T Do not use this form for proposals to drill or to re-enter an MAR 18 2010 abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreem SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other Ross Federal No. 5 2. Name of Operator McClellan Oil Corporation 9. API Well No. 30-005-63621 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area P.O. Box 730, Roswell, New Mexico 88202 Foor Ranch Wolfcamp (575) 622-3200 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660' FSL & 660' FEL of Section 7 - Township 10 South - Range 26 East 11. Country or Parish, State Chaves, New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Begin workover operations on 1/25/10.

- 1. Set CIBP at 5,230'. Dump bail 35' cement on top of bridge plug.
- 2. Perforate Wolfcamp zone from 5,030' to 5,034' with 4 shots per foot.
- 3. Acidize zone with 1,500 gallons 15% HCL with clay stabilizers
- 4. Swab test zone.
- 5. Well is currently shut in to evaluate zone for possible frac job.

TA/51 APPROVED FOR 90 MONTH PERIOD

Accepted for record NMOCD (CE) 3/18/10

ENDING JUN 0 6 2010

3/18/10	
14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>) Mark McClellan	Title President
	THE COMMIT
Signature MM: Collan	Date 03/03/2010
ACCEPTED FOR RECORIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by /S/ DAVID R. GLASS Conditions of approval, MAN are attached Officeroval of this notice does not warrant or or	Title Date
Conditions of approval, Wan are attached Unproval of this notice does not warrant or of that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.	ortify Office ROSWELL FIELD OFFICE

Title 18 U.S. C. Section DONALD RUCAL ASS. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudule at States and representations as to any matter within its jurisdiction.