FAX NO.

RECEIVED

APR 2 2 2010

Apr. 02 2010 10:40AM

Form 3160-5

UNITED STATES

FORM APPROVED

OMB No. 1004-0137 (August 2007) DEPARTMENT OF THE INTERIOR Expires: July 31, 2010 NMOCD ARTES! **BUREAU OF LAND MANAGEMEN** e Serial No. LC 029415 B SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribo Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on page 2. I, Type of Well R. Well Name and No. Z Oil Well [Other Gas Well Puckett North #3 2. Name of Operator Hudson Oil Company of Texas 9. API Well No. 30-015-36633 Je. Address 3b. Phone No. (include area vode) 10 Pield and Poul or Exploratory Area 818 Yexas Street Fori Worth, Texas 76102 Maljamer - Grayburg San Andres 817-338-7109 11. Country or Parish, State 4. Location of Well (Footage, Sec., T.R., M., or Survey Description) Eddy County, New Mexico 810' FSL & 2280' PWL Section 12 T178 - R 31E Unit "N" 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Deepen Acidize Notice of Intent Well Integrity] Fracture Tront Reclamation Alter Casing Other Completion Sundry **New Construction** Casing Repair Recomplete Subsequent Report Plus and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all portinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deopen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) **RU WOR** 12/02/08 MIRU Enertech Run GR, CCL Perf 3481' - 4129' @ 1 SPF for a total of 48 holes A/ perfs with 4000 gallons 15% NEFE 12/03/08 Frac w/ 629,746 galions of slick H20 carrying 280,680% sand @ 3562 PSI 12/06/08 12/12/08 PU & ran 157 jts 2-3/8" tbg set @ 3985' ND BOP ACCEPTED FOR RECORD 01/14/09 Turned well over to production BUREAU OF LAND MANAGEMENT ØARLSBAD FIELD OFFICE 14. I horoby cortify that the foregoing is true and correct. Name (Printed/Typed) Jon Smith Title Field SuperIntendent 04/02/2010 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agoncy of the United States any false. fictitious or fraudulum statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

that the applicant holds logal or equitable title to those rights in the subject lease which would