orm 3160-5 February 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APROVED		
OMB NO. 1004-0135		
EXPIRES: March 31, 2007		

X	M
1	"

MAY 26 2010 SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No Do not use this form for proposals to drill or to re-enter an LC-061783-B abandoned well. Use Form 3160-3 (APD) for such proppsats ACC ARTES 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. a. Type of Well Oil Well Gas Well Other 8 Well Name and No. Name of Operator Mann 3 Federal 4 **DEVON ENERGY PRODUCTION COMPANY, LP** 9 API Well No 3 Address and Telephone No. 30-015-35936 20 North Broadway, Oklahoma City, OK 73102-8260 10. Field and Pool, or Exploratory 405-552-8198 I. Location of Well (Report location clearly and in accordance with Federal requirements)\* Red Lake; Q-GB-San Andres 452 FSL 867 FWL 11. County or Parish State NM M 3 18S 27E Eddy 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OS SUBMISSION Production (Start/Resume) Water Shut-Off Acidize Deepen ☐ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Other Casing Repair New Construction Recomplete Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical Jepths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including eclamation, have been completed, and the operator has determined that the site is ready for final inspection) 12/28/2010 MIRU. POOH with rods and pump. NU BOP. POOH with tubing. 12/29/2010 Perforate San Andres 2102'-2324'; 1 spf; 37 holes RD. 12/30/2020 RIH with RBP and set at 2729'. RIH with packer and set at 2350'. Test RBP to 1500# - ok. Pull up and set packer at 2030'. Acidize perfs with 1500 gallons 15% HCI, 4000 gallons 30% Acetic acid, and 40,000 gallons fresh water. Flow well back 12/31/2009 Unset packer and POOH. RiH with production tubing. 1/02/2010 RIH with rods. Hang well on 2/05/2010 Unhang well and unseat pump POOH with rods and pump ND wellhead and NU BOP POOH with tubing. ND BOP NU frac valve. 2/08/2010 Frac San Andres perfs with 230,823 gallons Aqua Frac 1000 linear gel, 143,212# Brown sand, and 26,142# 16/30 Siber Prop. 2/09/2010 ND frac valve and NU BOP RIH with production tubing. ND BOP and NU wellhead RIH with pump and rods. Hang well on and return to production 2/10/2010 Release all equipment and RDMO 14. Thereby certify that the foregoing is true and correct Name Norvella Adams Title Senior Staff Engineering Technician Date (This space for Federal or State Office use) Approved by Title Date Conditions of approval, if any: Title 16 0 5 C. Section 1001, makes it a crime for any person knowingly within its jurisdiction \*See Instruction on Reverse Side

BUREAU OF LAND MANAGEMENT ARLSBAD FIELD OFFICE