an

Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr , Hobbs, NM 88240 District II 30-005-63037 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🛛 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 State Oil & Gas Lease No. District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 V-2982 7. Lease Name or Unit Agreement Name: SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A **Quincy AMQ State** DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well No. 5 1. Type of Well: Oil Well ⊠ Gas Well Other Name of Operator 9. OGRID Number 2. JUN 11 2010 Hanson Operating Company, Inc. 009974 Address of Operator 10. Pool name or Wildcat 3. PO Box 1515, Roswell, NM 88202-1515 NMOCD ARTESIA Acre San Andres Southeast Well Location Unit Letter E feet from the North line and 990 feet from the West : 1650 line Section 12 Township 8-S Range 27- E **NMPM** County Chaves 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3968' GR Pit or Below-grade Tank Application or Closure Pit type \_ Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Below-Grade Tank: Volume Pit Liner Thickness: bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. P AND A **PULL OR ALTER CASING MULTIPLE** CASING/CEMENT JOB COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 05/03/10 MIRU rig and cementing equipment. Dig out cellar, NU BOP, RIH and Set CIBP @ 2050'. Circulate hole w/ mud laiden fluid. Spot 25 sx class C cement on top of CIBP. Perf'd csg @ 497'. ND BOP and Sqz and Circulate cement to surface w/ 140 sx class C cement. ND BOP. Rig down move off. Move in welder and backhoe. Cut off wellhead and weld on Dry Hole Marker, Back fill cellar. Clean loc. Move off. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan. **SIGNATURE** TITLE Production Analyst DATE 6/9/2010 Type or print name Carol J. Smith E-mail address: hanson@dfn.com Telephone No. 575-622-7330 For State Use Only Approved for plugging of well bore only. Liability under bond is retained pending receipt APPROVED BY TITLE DATE 6 of C-103 (Subsequent Report of Well Plugging) which for the browned it OCD Web Page under which for the browned by Forms On A-Disk · (214) 340-9429 · Forms On ADisk.com Forms, www.cmnrd.state.nm.us/ocd. Conditions of Approval (if any):