Office		New Mex			Form C-1	
District I	Energy, Minerals	and Natura	al Resources		October 13, 20)09
1625 N. French Dr , Hobbs, NM 88240			WELL API NO.			
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION			30-015-24305			
1301 W. Grand Tive., Thresia, Tivi 00210			5. Indicate T	vpe of Lease		
District III	1220 South St. Francis Dr.			STAT		
1000 R ₁₀ Brazos Rd , Aztec, NM 87410	Santa Fe, NM 87505				& Gas Lease No.	-
<u>District IV</u> 1220 S. St. Francis Dr , Santa Fe, NM		-, - 111 - 0 / 1		0. State Off &	e Gas Lease No.	
87505						
	S AND REPORTS O	NWELLS		7 Lease Nan	ne or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC			G BACK TO A		ark SWD	´
DIFFERENT RESERVOIR USE "APPLICAT				Cia	ark SWD	
PROPOSALS)	(-	,,.				
1. Type of Well: Oil Well Gas Well Other		RECEIVED		8. Well Num	ber 001	
2. Name of Operator		I NECLIVED		9. OGRID N	umber	
Mesquite SWD, Inc		7 2010		161968		
3. Address of Operator		JUL 7 2010		10. Pool name or Wildcat		
P.O. Box 1479 Carlsbad, NM 88221						
			NMOCD ARTESIA		SWD	
4. Well Location		1411.				
Unit Letter G:	1650 feet from the	N	line and	2310 fe	et from the \underline{E} 1	ine
Section 11			Range 28E	NMPM	Eddy County	<i>III.</i>
	1. Elevation (Show w	hether DR, .	RKB, RT, GR, etc	.)		Riv.
	. 3222'					
12 Check An	propriate Box to In	dianta Na	tura of Motica	Danart or Ot	har Data	
12. Check Ap	propriate box to in	iuicate iva	itule of Notice,	Report of Ot	nei Data	
NOTICE OF INT	ENTION TO:	i	CLIE	OCCOLIENT.	DEDODT OF	
				REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO				_	ALTERING CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS. ☐ P AND A ☐]
PULL OR ALTER CASING 1	MULTIPLE COMPL		CASING/CEMEN	IT JOB [7	
DOWNHOLE COMMINGLE		_			_	
50,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				,		
OTHER:			OTHER: MI	т	Y	
13. Describe proposed or complete	ad operations (Clear)	v state all p			datas including actimated	doto
						uate
of starting any proposed work		.14 NMAC.	. For Multiple Co	impletions: Atta	ich wellbore diagram of	
proposed completion or recom	ipletion.					
7/6/2010 Ran MIT under obse	ervation of OCD Richa	ard Inge. Pi	ressure held for 30) min. Well read	dy to receive disposal. Wai	ting
on electricity.						
I haveby cartify that the information ob	ave is true and comple	to to the hor	t of my knowled	on and haliaf		
I hereby certify that the information abo	ove is true and comple	te to the bes	st of my knowled	ge and belief.		
		te to the bes	st of my knowleds	ge and belief.		
Kan Hay	mol			ge and belief.		
I hereby certify that the information about SIGNATURE KAY HAVE			st of my knowleds Agent	ge and belief.	DATE 7 <u>/6/2010</u>	
SIGNATURE KAY HAVE	TIT	LE	Agent		DATE 7 <u>/6/2010</u>	
Kan Hay	TIT	LE			DATE 7/6/2010 PHONE: 575-622-0283	
SIGNATURE KAY HAVE	TIT	LEail address:	Agent KHavenor@geo			
SIGNATURE KAY HAVENOR Type or print name Kay Havenor	TIT	LEail address: For State	Agent KHavenor@geo Use Only	resources.com		
SIGNATURE Kay Havenor Type or print name Kay Havenor	TIT E-m	LEail address: For State	Agent KHavenor@geo Use Only	resources.com	PHONE: <u>575-622-0283</u>	
SIGNATURE KAY HAVE	TIT	LEail address: For State	Agent KHavenor@geo	resources.com		