RM

JUN 14 2010 DEFARTMEN BUREAU OF L. NMOCD APPLES A DO NOT USE this form for p abandoned well. Use Form SUBMIT IN TRIPLICATE- C. 1 Type of Well	T OF THE INTERIOR AND MANAGEMENT AND REPORTS ON V roposals to drill or to a 3160-3 (APD) for such Other instructions on re Other 3b Phone No. (in 432-685-4385	re-enter an proposals. verse side.	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5 Lease Serial No. NMNM-86025 6. If Indian, Allottee or Tribe Name N/A 7. If Unit or CA/Agreement, Name and/or No. N/A 8. Well Name and No. McIntyre DK Federal #17 9 API Well No. 30-015-37821 10. Field and Pool, or Exploratory Area Loco Hills; Glorieta-Yeso 11 County or Parish, State
Eddy, NV			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION			NETONI, ON OTHER DATA
Acidize Acidize Alter Casin Subsequent Report Final Abandonment Notice Acidize Casing R Change Pla Convert to	Deepen Fracture Treat Plug and Aband	Production (St Reclamation on Recomplete	Well Integrity Other Change Drilling Plan bandon
Describe Proposed or Completed Operation (clearly state all pertunent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertunent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) COG Operating LLC respectfully requests permission to make the following changes to the drilling program:			
Hole Size Interval OD of Casing 17-1/2" 0' - +/-425' 13-3/8"	Weight Thread Collar 48# New STC	Grade	2 724 Puret of 9 71 Tangian of 14 01
17-1/2" 0' - +/-425' 13-3/8" 48# New STC H-40/J-55 Collapse sf - 3.724, Burst sf -8.71, Tension sf -14.91 Cement with: 500sx Class C, yield 1.32			
12-1/4" 0' - +/-1400' 9-5/8" 40# New STC K-55 Collapse sf - 3.45, Burst sf -4.43, Tension sf -5.68 Lead: 200sx C w/ 50:50:10, yield 2.45. Tail: 200sx Class C, yield 1.32.			
8-3/4" 0' - +/-4850' 7" 26# New LTC P-110 Collapse sf -3.45, Burst sf -4.43, Tension sf -5.68 Lead: 500sx C w/ 4% gel, yield 1.72. Tail: 200sx C w/ 50:50:2, yield 1.33. 6-1/8" 4850' - +/-8985'MD 4-1/2" 11.6# New LTC P-110 Collapse sf -4.20, Burst sf -4.75, Tension sf -4.80 +/-4950'TVD			
14 Thereby certify that the foregoing is true and Name (Printed/Typed)	correct		
Robyn M. Odom	Titl	Regulatory Analyst	
Signature Co C	Dat Dat	e	06/03/2010
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by Conditions of approval, if any, are attached Approval certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operation. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1 States any false, fictitious or fraudulent statements or respectively.	o those rights in the subject lease s thereon 212. make it a crime for any person	Title Office n knowingly and willfully in its jurisdiction.	APPROVED Petroleum Engineer to make to any dispartinent of 200ky of the United /s/ Roger Hall
(Instructions on page 2)	-		BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

mz

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: COG

LEASE NO.: | NMNM86025

WELL NAME & NO.: McIntyre DK Fed #17
SURFACE HOLE FOOTAGE: 940' FSL & 380' FWL
BOTTOM HOLE FOOTAGE 990' FSL & 660' FEL

LOCATION: Section 17, T. 17 S., R 30 E., NMPM

COUNTY: Eddy County, New Mexico

I. DRILLING

A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOPE tests

Eddy County

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. A Hydrogen Sulfide (H2S) Drilling Plan should be activated 500 feet prior to drilling into the Grayburg formation. As a result, the Hydrogen Sulfide area must meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, please provide measured values and formations to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 3. The record of the drilling rate along with the CAL/GR/N well log run from TD to surface will be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

B. CASING

Changes to the approved APD casing and cement program require submitting a sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

Possible brine and water flows in the Salado and Artesia groups. Possible loss of circulation in the Grayburg and San Andres formations.

- 1. The 13-3/8 inch surface casing shall be set at approximately 425 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
 - □ Cement to surface. If cement does not circulate see B.1.a, c-d above. Casing to be set in the Seven Rivers formation.

Centralizers required on horizontal leg, must be type for horizontal service and minimum of one every other joint.

- 3. The minimum required fill of cement behind the 7 inch production casing is:
 - ☐ Cement to surface. If cement does not circulate see B.1.a, c-d above.
- 4. The minimum required fill of cement behind the 4-1/2 inch production liner is:
 - No cement required Packer system being used. Variance for the 100 foot overlap is approved.
- 5. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000 (2M)** psi.
 - a. **For surface casing only:** If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 3. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. Casing cut-off and BOP installation will not be initiated until the cement has had a minimum of 8 hours setup time for a water basin. The casing shall remain stationary and under pressure for at least eight hours after the operator places the cement. In the potash area, the minimum time is 12 hours and the casing shall remain stationary and under pressure during this time period. Casing shall be under pressure if the operator uses some acceptable means of holding pressure or if the operator employs one or more float valves to hold the cement in place. Testing the BOP/BOPE against a plug can commence after meeting the above conditions plus the BOP installation time.
 - b. The tests shall be done by an independent service company using a test plug.

- c. The results of the test shall be reported to the appropriate BLM office.
- d. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- e. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

RGH 060910