

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 May 27, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-005-64022
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Crystal Diamond
8. Well Number 133
9. OGRID Number 259169
10. Pool name or Wildcat Chaves Undesignated MISS Gas

RECEIVED
 JUL 26 2010
 NMOCD ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TO RE-ENTER AN EXISTING WELL IN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator Waterford Operating LLC.

3. Address of Operator 1001 McKinney STE. 2000 Houston TX. 77002

4. Well Location
 Unit Letter J : 1980 feet from the south line and 2492 feet from the east line
 Section 33 Township 12s Range 28e NMPM chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3599

Pit or Below-grade Tank Application or Closure

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water N/A

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

Notify OCD 24 hrs. prior to any work done.

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1. notify OCD. 48 Hrs. before move in.
- 2. M.I.R.U. N.D.W.H. N.U. B.O.P.
- 3. Unset PKR. POOH. Tbg. & PKR.
- * 4. RIH. Tbg. Tag existing CIBP @ 7705, Circ hole w/ MLF. Cap w/ 25 sxs cmt.
- * 5. PUH to 6000, spot 25 sxs cmt.
- * 6. PUH to 4000, spot 25 sxs cmt. WOC Tag.
- 7. PUH to 2100, spot 25 sxs cmt.
- * 8. PUH to 1750, spot 25 sxs cmt. WOC Tag.
- * 9. PUH to 60, spot 20 sxs cmt. to surface.
- 10. R.D.M.O.

*-> Formations to be isolated with plugs placed at top of each formation. 100' cmt plug.

- *- Wolfcamp - 6194'
- *- Abo - 5150'
- *- Glorietta - 2935'
- *- Yates - 335'

* 8 5/8" shoe @ 1205' 50' above & 50' below. WOC Tag

* 11 3/4" shoe @ 347' 50' above & 50' below WOC Tag.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE [Signature] TITLE Regard (Basic Energy Services) DATE 7-22-10

Type or print name: _____ E-mail address: _____ Telephone No. 432-530-0907

For State Use Only

APPROVED BY: [Signature] TITLE _____ DATE 7/27/2010
 Approval Granted providing work is complete by 10/27/2010

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CIRC)

OPERATOR WATERLOO
 BASENAME CRYSTAL DIAMOND 175
 WELL # _____

SECT _____ TWIN _____ RING _____
 FROM _____ NSL _____ EWL _____
 TO: _____ FORMATION @ TD _____
 PETD: _____ FORMATION @ PETD _____

113/4
@ 340
 TOC SPT-400
250 SPT-400

4 5/8
@ 1905
 TOC SPT-600
275 SPT-600

CIBP 2705
E. Per 7654 - 7650


5 1/2
@ 7914
 TOC SPT-600
475 SPT-600

TO 7920

	SIZE	SET @	TOC	TESTED BY	
SURFACE					
INTMED 1					
INTMED 2					
PROD					
	SIZE	TOP	EOT	TOC	TESTED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1				DEPTH	-
INTMED 2				DEPTH	-
PROD					

PLUGGING & ABANDONMENT WORKSHEET @ STATIC CHRG.

OPERATOR Waterford
 LEASENAME Crystal Diamond 125
 WELL # _____
 SECT _____ TWIN _____ RING _____
 FROM _____ NSL _____ SWL _____
 TO: _____ FORMATION @ TD _____
 PBD: _____ FORMATION @ PBD _____



	SIZE	SET @	TOC	TOC ESTABLISHED BY
SURFACE				
INTMED 1				
INTMED 2				
PROD				
	SIZE	TOP	EOT	TOC ESTABLISHED BY
LINER 1				
LINER 2				
	CUT & PULL @			TOP - BOTTOM
INTMED 1			PLUG	-
INTMED 2			PLUG	-
PROD				

CISP 2705
E. Part 7654 - 7650

TO 1920