	<u> </u>	EIVED	
TAR.	TE (5)	25.2010	I B
\	Kon	ARTE	SIAL

TED \	OCD	-ARTESIA					
UNITED STATES A  UNITED STATES  DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT  OF ARTESIA  OCD-ARTESIA  UNITED STATES  DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB No 1004- 0137 Expues July 31, 2010		
BUREAU OF LAND MANAGEMENT  AND 25 2010  BUREAU OF LAND MANAGEMENT  NMOCD ARTESIA  BUREAU OF LAND MANAGEMENT  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					5 Lease Serial No NMLC028784B 6 If Indian, Allottee, or Tribe Name		
SUBMIT IN TRIPLICATE - Other Instructions on page 2.					7 If Unit of CA Agreement Name and/or No NMNM88525X		
Type of Well Gas Well	X Other WIW				8 Well Name and No		
2 Name of Operator Marbob Energy Corporation					ch Keely Unit #144		
3a Address	9 API Well No						
PO Box 227 (575)			48-3303		30-015-04389		
Artesia, NM 88211-0227  4 Location of Well (Footage, Sec., T. R. M., or Survey Description)					Jackson; SR-Q-Grbg-SA		
					arish, State		
660 FNL 1980 FWL, Sec. 30-T17S-R30E, Unit C Eddy Co., NM							
12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize	Deepen	Productio	n ( Start/ Resume)	Water Shut-off		
	Altering Casing	Fracture Treat	Reclamate	ion	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomple	ete	Other		
	Change Plans	Change Plans X Plug and Abandon Temporarily Abandon					
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dis	sposal			
Attach the Bond under which the work will performed or provide the Bond No on file with the BLM/ BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)  6/21/10 - 6/28/10							
This well has been plugg	ged & abandoned.			ACCEPTE	D FOR RECORD		
(See detailed procedure attached)					DIONINLOOND		
Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.				BURFAU C	OF LAND MANAGEMENT OF BAD FIELD OFFICE		
Redamation Due 12-22-10							
14 Thereby certify that the foregoing i Name (Printed Typed)	s true and correct	1					
Diana	J. Briggs	Γitle		Production Ma	mager		
Signature ) ) ( )	Date		July 27, 2010				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Anniqued by		T.d.					
Approved by Conditions of approval, if any are attaccentry that the applicant holds legal or				Da	Ie .		
which would entitle the applicant to conduct operations thereon.  File 18 U.S.C. Section 1001 AND File 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United							
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction							

## MARBOB ENERGY CORPORATION BURCH KEELY UNIT #144 (WIW) - P&A 660 FNL 1980 FWL, SEC. 30-T17S-R30E, UNIT C 30-015-04389; GRBG JACKSON; SR-Q-GRBG-SA EDDY COUNTY, NM

- 6/21/10 **P&A:** MI. PREP TO RU. CANNOT FIND 1 ANCHOR. WAIT ON T&C TO SET NEW ANCHORS. RU. NU BOP. UNSET PKR. POOH & LD 76 JTS 2 3/8" TBG. SECURE WELL. SDFTN.
- RIH W/ TBG. TAG PLUG @ 797'. POOH. RU E-LINE. PERF 8 SQZ HOLES @ 558'. RIH W/ PKR. SET @ 317'. MIX 96 SX C W/ 2% CACL. DISP W/ 1.7 BBLS BRINE GEL. RLS PKR. POOH. WAIT 3 HRS. RIH W/ TBG. TAG @ 301'. POOH. RU E-LINE. SHOOT 8 SQZ HOLES @ 200'. RIH W/ 8 JTS 2 7/8" TBG TO 260'. SPOT 45 SX CLASS C W/ 2% CACL. POH. ND BOP: RMV W/H. INSTALL 7" SWEDGE. MIX 178 SX CLASS C W/ 2% CACL. DID NOT CIRC UP 8 5/8" ANNULUS. FLUSH TO CSG. WELL ON VAC. SECURE WELL. SDFTN.
- 6/24/10 RIH W/ TBG. TAG CMT @ 7' FR/ SURF. RU TO 8 5/8" ANNULUS. BEGIN PMPG CMT. CIRC OUTSIDE SURF W/ 2 BBLS (8 SX). RD CEMENTERS. RD RIG. RETURN TO BKU YARD: 76 JTS 2 3/8" TBG & 78 JTS 2 7/8" WORKSTRING.
- 6/28/10 DRY HOLE MARKER SET & ANCHORS REMOVED. FINAL REPORT.

\*\*\*PLUGGED AND ABANDONED\*\*\*

ERGY CORPORATION
BURCH
660

G JACKSON; SR-Q-GRBG-SA COUNTY, NM

- 6/21/10 P&A: MI. PREP TO RU. CANNOT FIND 1 ANCHOR. WAIT ON T&C TO SET NEW ANCHORS. RU. NU BOP. UNSET PKR. POOH & LD 76 JTS 2 3/8" TBG. SECURE WELL. SDFTN.
- 6/22/10 RU W/L. RIH W/ CIBP. SET @ 2500'. POOH. SHOOT 8 SOZ HOLES @ 995'. RD W/L. PU & TIH W/ 78 JTS 2 7/8" TBG. TAG CIBP. RU CMTRS. CIRC HOLE W/ 95 BBLS BRINE GEL. SPOT 30 SX CLASS C W/ 2% CACL. POOH W/ TBG. PU & TIH W/ PKR. SET @ 701'. EST INJ RATE OF 2 BPM @ 152#. MIX 96 SX C CMT W/ 2% CACL. DISP W/ 4.6 BBLS BRINE GEL. TBG STATIC. POOH W/ PKR. SECURE WELL.
- 6/23/10 RIH W/ TBG. TAG-PLUG-@-797'. POOH. RU E-LINE. PERF 8 SQZ HOLES @ 558'. RIH W/ PKR. SET @ 317'. MIX 96 SX C W/ 2% CACL. DISP W/ 1.7 BBLS BRINE GEL. RLS PKR. POOH. WAIT 3 HRS. RIH W/ TBG. TAG @ 301'. POOH. RU E-LINE. SHOOT 8 SQZ HOLES @ 200'. RIH W/ 8 JTS 2 7/8" TBG TO 260'. SPOT 45 SX CLASS C W/ 2% CACL. POH. ND BOP. RMV W/H. INSTALL 7" SWEDGE. MIX 178 SX CLASS C W/ 2% CACL. DID NOT CIRC UP 8 5/8" ANNULUS. FLUSH
- 6/24/10 RIH W/ TBG. TAG CMT @ 7' FR/ SURF. RU TO 8 5/8" ANNULUS. BEGIN PMPG CMT. CIRC OUTSIDE SURF W/ 2 BBLS (8 SX). RD CEMENTERS. RD RIG. RETURN TO BKU YARD: 76 JTS 2 3/8" TBG &
- 6/28/10 DRY HOLE MARKER SET & ANCHORS REMOVED, FINAL REPORT.

\*\*\*PLUGGED AND ABANDONED\*\*\*