Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000

## 5. Lease Serial No.

S	NMNM041

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

SUNDRY NOTICES AND REPORTS ON WELL

17696 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. #12 Lost Tank 4 Federal 9. API Well No.

1. Type of Well X Oil Well Gas Well Other 2. Name of Operator OXY USA Inc. 16696 3a. Address 3b. Phone No. (include area code) 30-015-3<u>7</u>955 P.O. Box 50250, Midland, TX 79710-0250 432-685-5717 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Lost Tank Delaware, West SL - 2200 FSL 2260 FWL NESE(K) Sec 4 T22S R31E BHL- 1941 FSL 412 FWL NWSW(L) 11. County or Parish, State NM Eddy 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Well Integrity Reclamation Subsequent Report Casing Repair New Construction Other Completion Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

RUPU 11/28/10, Drill out DV Tools and clean out to PBTD @ 8425'. Perf 1 SPF 8442-8438, 8338-8330, 8262-8258, 8234-8230, 8196-8192, 8120-8112, 8082-8078, 7936-7932, 7912-7908, 7720-7714, 7700-7694, 7586-7582, 7568-7564, 6956-6950, 6892-6884, 6836-6832, 6744-6740, 6706-6704, 6686-6684' Total 90 holes. Frac w/ 69090g Treated Water followed by 8000gal 7-1/2% NeFe HCl acid followed by 18125gal Water Frac GR-21 followed by 157633gal Delta Frac 200 R-16 w/ 157633# sand, RD Halliburton. Swab and flow back to clean up well. RIH w/ 2-7/8" tbg and rod pump, Put well on pump 12/24/10 and test well for potential. Shut-In well.

JAN **28** 2011

			NMOCD ARTE	SIA
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart	Title	Sr. Regulator	Analyst IFD FO	R RECORD
Un Stat	Date	1/6/11		
THIS SPACE FOR FEDERAL	L OR ST	ATE OFFICE US	E   1AM 2.2	2011
Approved by	Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.	se		BURFAU OF LAND	MANAGEMENT
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for an	y person k	nowingly and willfull	y to make to any department	or agency of the United

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.