

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY N. M. O. C. C. PY

Form approved by *Copy 65F*
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

3. LEASE DESIGNATION AND SERIAL NO. **LC 064832**
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL GAS WELL OTHER **WATER INJECTION**

7. UNIT AGREEMENT NAME **FOREST POOL**

2. NAME OF OPERATOR **CONTINENTAL OIL COMPANY**

8. FARM OR LEASE NAME **FOREST POOL UNIT**

3. ADDRESS OF OPERATOR **Box 460, HOBBS, N.M. 88240**

9. WELL NO. **14**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1650' FSL & 1650' FEL OF SEC. 34

10. FIELD AND POOL, OR WILDCAT **SQUARE LAKE G-SA**
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA **SEC. 34 T-16S, R-29E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3663' DF J.C.C. ARTESIA, OFFICE

12. COUNTY OR PARISH **EDDY** 13. STATE **N.M.**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

*There are no remaining commercial reserves on this lease. All wells will be plugged; the above named well by the following procedure:
Remove tubing. Run tubing w/cement retainer to set @ 2350'. Squeeze open hole w/250 sks. Class "C" cmt. Will not reverse out any excess. Pull out retainer & spot 25-50 sks. cmt above retainer.
Pull tubing to 500' & spot 100 sks plug to stc.
Erect Dry Hole marker.*

(No casing will be removed.)

I hereby certify that the foregoing is true and correct
SIGNED *[Signature]* TITLE **SR. ANALYST** DATE **12-10-75**

(This space for Federal or State office use)

APPROVED BY *[Signature]*
CONDITIONS OF APPROVAL, IF ANY:
APR 13 1976
H. C. BEEKING
ACTING DISTRICT ENGINEER

RECEIVED

DEC 12 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

*See Instructions on Reverse Side

ARTESIA
USGS-5, Partner, File