NO. OF COPIES RECEIVED			France (2.) 22
DISTRIBUTION	Form C-103 Supersedes Old		
SANTA FE /	C-102 and C-103 Effective 1-1-65		
FILE i	NEW MEXICO OIL CONSERVA		Ellective 1-1-65
U.S.G.S.	IUL.	. 2 0 1973	5a. Indicate Type of Lease
LAND OFFICE		. 2 0 13/3	State XX Fee
OPERATOR /			5. State Oil & Gas Lease No.
		. C. C.	507/0
SUNDR	I NO LICES AND REPORTS ON WELL		
1. CIL GAS WELL 2. Name of Operator	OTHER-		7. Unit Agreement Name
Sun Oil Company	V		8. Farm or Lease Name Continental "U-#5"
3. Address of Operator	9. Well No.		
	Midland, Texas 79701		1
4. Location of Well UNIT LETTER	330 FEET FROM THE North	2310 FEET FROM	10. Field and Pool, or Wildcat Grayburg Jackson
	N15	29-Ē	
	15. Elevation (Show whether DF, RT		
	12. County		
$\frac{16}{16}$	3518 DF	······································	Chaves ()
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON X		T REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
		HER	
OTHER			_
1. MIRU pulling Unit. 2. Pull rods and 2 3/ 3. Run 2 3/8" tubing 4. Spot 25 sx cement 5. Shoot and pull 4 1 6. Spot 30 sx cement 7. Spot 35 sx cement 8. Place 10 sx cement and clean location	8" tubing. open ended and load hole wit plug in 4 1/2" casing from 2 /2" casing at free point (es plug from 50' inside 4 1/2" plug from 750 to 650 across plug at surface, weld cap of	th 9.5# mud. 1625 to 2325 it 2000') TOC 2050' across stub into op 7 5/8" casing seat, on 7 5/8", install p	oen hole.
10. I hereby certify that the information ab	pove is true and complete to the best of my kno	wledge and belief.	
SIGNED Charles R. P. N.	Engi	neer	7-13-73

ONDITIONS OF APPROVAL, IF ANY:

As yroted above

Plugging

Notify N.M.O.C.C. in sufficient time to witness

flugging

OIL AND GAS INSPECTOR

JUL 3 1 1973

		-			
		1			
				-	
					- * .
4 9 <u>1</u>		•			
39 3		s s			
		b			1