

30-015-03212

M. 32-175-29c

Webb Oil Co.

Old Loco UT #13.

Tops

SALT - 3W: 710.

Antly. 1070!

* Perforate 5 1/2" casing @ 30'. Circulate cement to surface.

* Perforate 5 1/2" csg @ 410'. Squeeze 100' cement Plug.
Inside + Outside 5 1/2" csg. TAG

* Perforate 5 1/2" csg @ 765'. Squeeze 100' cement Plug
Inside + Outside 5 1/2" csg. TAG

* Circulate brine gel.

* Spot 2558 cement Plug 2504'-2604'. TAG

* T. Pert. - 2504' - 16'.

5 1/2"

2700'

w/100ss

7" casing

8 5/8"

360'

w/100ss

Casing
Bowl
Tie-back.

w/25ss