

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 060528Unit Maddren-Bosson, BUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loco Hills, N. M. Feb. 28, 1955Well No. 2-B is located 1650 ft. from N line and 330 ft. from W line of sec. 27NW/4, SW/4, Sec. 27 17-S 30-E N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)Premier Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3632 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)
RECORD OF PRODUCTION PRIOR TO TREATMENT: Pumped 4 BOPD. Total Prod. 73.574 BO.

RECORD OF RECOMPLETION: (1955)

2-3 Ram 3214' of 2-1/2" RBE tubing with Guilberson G-2 B-W packer at 2965'.
Loaded annulus.

2-4 Fractured as follows: 6 bbls. crude; 37 bbls. kerosene; 235 bbls. 24 gravity refined oil containing 14,500 lbs. sand. Flushed with 50 BO. Max. inj. press. 3500 psig; at end of flush 2400 psig, dropping to 1800 psig on stopping pump. Total inj. time 31 min. Load oil 380 bbls.

RESULTS OF TREATMENT:

2-5 Re-ram pumping installation.

2-6 Pumped & flowed 100 bbls. in 18 hrs.

2-7 Pumped 88 bbls.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Continued on page #2

Company GENERAL AMERICAN OIL COMPANY OF TEXASAddress BOX 416LOCO HILLS, NEW MEXICO

By

R. J. Heard
Title Field Supt.

General American Oil Co. of Texas

Page #2

Subsequent Report of Sandeill
Maddren-Beeson B-2

Feb. 28, 1955

RESULTS OF TREATMENT (cont'd).

2-8 Pumped 90 bbls.
2-9 Pumped 86 bbls.
2-10 Pumped 64 bbls. (NET 48 BO).

SUBSEQUENT TESTS:

2-16 Pumped 46 BO.

Page 15
Feb. 28, 1935

(General American Oil Co. of Texas

Subsequent Report of Randolph
Madison-Benson 8-2

RESULTS OF TREATMENT (cont'd).

2-8 Pumped 20 gals.
2-9 Pumped 20 gals.
2-10 Pumped 20 gals. (not 10 gals.)

SUBSEQUENT TESTS:

2-18 Pumped 16 gals.

