

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

R.O. BOX 2088

Form C-103
Revised 10-1-73

RECEIVED BY E. NEW MEXICO 87501

AUG 28 1986

O. C. D.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-4108	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS FOR DRILLING BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>P&A WEL</u>		7. Unit Agreement Name
2. Name of Operator <u>Yates Petroleum Corporation</u>		8. Farm or Lease Name <u>Tallmadge</u>
3. Address of Operator <u>105 South 4th St., Artes-a, NM 88210</u>		9. Well No. <u>4</u>
4. Location of Well UNIT LETTER <u>N</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>17S</u> RANGE <u>30E</u> NMPM.		10. Field and Pool, or WHcat <u>Loco Hills-O-G-SA</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3557' DF</u>		12. County <u>Eddy</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-26-86. RUPU. Picked up 95 jts of 2-3/8" tubing. Tagged bottom at 2907.34'.

8-27-86. Plugged well as follows:

Spotted 100 sx Class "C" cement w/4% CaCl2 at 2910'. Tagged plug at 1850'. Perforated w/2 .50" squeeze holes at 1225'. Squeezed Base of Salt (1225') to 700# w/50 sx Class "C" w/4% CaCl2. Tagged cement at 1140'. Perforated squeeze hole at 425' (Top of Salt). Squeezed Top of salt w/50 sx Class "C" w/4% CaCl2 to 600#. Tagged cement at 260'. Spotted 10 sx Class "C" Neat plug at 30' to surface. Installed regulation abandonment marker. Plugging witnessed by NMOC, Artesia, NM.

Post FD-2
9-19-86
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Guyana Doodler TITLE Production Supervisor DATE 8-28-86

APPROVED BY OK G.W. 12-28-89 TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: