

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

C. Cons.
N.M. Div-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210
Bureau No. 1004-0135
Expires August 31, 1985
FILE NO. DESIGNATION AND SERIAL NO.
LC-029418 B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR
The Wiser Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 1980' FEL
Unit B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Lea "C"

8. WELL NAME AND NO.
2

9. API WELL NO.
30-015-05130

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson 7RVS-QN-GB-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 11-T17S-R31E

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3968' DF

12. COUNTY OR PARISH
Eddy County

13. STATE
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT * ☒

(Other) Return to Production

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/25/01 MIRU Tyler WS # 103. ND WH. RU BOP. POH w/2-3/8" IPC tbg. LD 5-1/2" AD-1 pkr. RIH w/4-3/4" bit, scraper & 2-7/8" tbg. to 3530'. POH w/2-7/8" tbg. LD tools.

6/26/01 Computalog WL perforated Seven Rivers f/2340', 41', 45', 50', 51', 53', 58', 59', 60', 67', 75', 76', 79', 80', 91', 98', 99', 2400', 05', 06', 20', 21', 22', 39', 40', 61', 82', 88', 92', 93', 94', 2507', 12', 32', 33', & 34' w/4 SPF. RD WL. RIH w/5-1/2" RBP, pkr. & 2-7/8" tbg. to 2598'. Set RBP & tested to 3200#. Spotted 300 gals. 15% NE-FE acid across perms. Set pkr. @ 2250'. Formation broke w/2000#. Acidized Seven Rivers 2340'-2534' w/3000 gals. 15% NE-FE acid & 3000# rock salt. Best block 1200#. Best break 1100#. ATP 1900# @ 3.3 bpm. MTP 2700# @ 3.5 bpm. ISIP 1500#. 5 min. 1460#. 10 min. 1440#. 15 min. 1430#. Flushed w/20 bbls. fresh water. 1 hr. SI 1370#.

6/28/01 RIH & picked up RBP. POH w/2-7/8" tbg. LD tools. RIH w/5-1/2" CIBP on 2-7/8" tbg. to 3370'. Set plug. LD tbg. RIH w/ 2-3/8" tbg. Tbg. @ 2643'. SN @ 2611'.

6/29/01 RD BOP. NU WH. RIH w/rods and 1-1/2" x 12' pump. Left well pumping 07/04/01.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II DATE July 16, 2001

(This space for Federal or State office use)

APPROVED BY Record only TITLE
CONDITIONS OF APPROVAL, IF ANY:

*See Instruction On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

