6-USCS-EDDY-ROSWELL 1-FILE 1-ENGR-PS 1	-FOREMAN-ED FOWLER 1-BB
Form 9-331 Dec. 1973	COMISSION Form Approved.
Form 9-331 NW OIL CONS.	Budget Bureau No. 42–R1424
	53.2 LEA SE
DEPARTMENT OF THE INTERIORATES 12. NA	LC-029418 (D)
C/SF GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME RECEIVED
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME OCT 2 0 1981
1 oil gas —	Skelly Unit
1. oil gas other Injection Well other Injection Well	9. WELL NO. 105 ARTESIA, OFFICE
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Getty Oil Company / 3. ADDRESS OF OPERATOR	Lily Jackson
P.O. Box 730; Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 14, T-17-S, R-31-E
below.) AT SURFACE: Unit Ltr. F 1980 FNL & 1980 FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	
AT TOTAL DEPTH:	Eddy Rew Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	3909 GL 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	71. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	TWIE THE SECTION OF SECTION
REPAIR WELL	(NOTE) report results of multiple completion or zone
PULL OR ALTER CASING AMULTIPLE COMPLETE	1981 / 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
CHANGE ZONES □ □	1981 And the state of the state
ABANDON* U.S. GEOLOGIC	GAS 19 Dog brigg 19 Strain Str
(other) ROSWELL, NE	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
and of pierrod up Bongo Well Service. POH	with tubing & Packer. Ran Dic
and scrapper. Cleaned out fill from	om 3690 to 3721 10 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
and scrapper. Cleaned out fill from 9-29-81 Set packer @ 3668'. Knox Services	acidized as follows:
$c_{+ace} = 1.$ Perfs: $3694-3/0$	4. Tare dare the and so pare
sealers. Max. Press. 2700#; Min. Press. 1000#, ISIP 2250#, 15 min. 1750#. Pulled	
packer. Set BP @ 3669. Set packer @	
3277'.	Through the second of the seco
State #2: Perfs: 3324-362	6'. 2706 gals. 15% NE and 150 ball
sealers.	Max. 2400#; Min. 1200#; ISIP 2000#. PM; 15 min. 1800#.
	그 하는 그는 그는 그는 그는 그 가는 그를 하는 것이 되었다. 그는 그는 그는 그는 그를 하는 그를 하는 그를 하는 그를 하는 것이다.
Subsurface Safety Valve: Manu. and Type	
18. I hereby pertify that the foregoing is true and correct	October 12 1981
SIGNED SIGNED TITLE Area Superin	ntendent October 12, 1981
ACCEPTED FOR RECORDS space for Federal or State	office use)
PETER W CHESTER THE	
CONDITIONS OF APPROVAL, IF ANY:	norned neibni anolislasjan vanibesona vanibesona vanibesona vanibesona vanibesona vanibos distribusi puda svoda voda voda voda voda voda voda voda
0CT 1 6 1981	osania H H Sha m Sha m Sha m Sha m Sha m Sha m Sha m
U.S. GEOLOGICAL SURVEY	8852 8 832
ROSWELL, NEW MEXICO See Instructions on Rever	se Side