Form 3160-5 (June 1990)

UNITED STATES DEPARTME OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OIL CONSERVATION DIV 9.5 s(S). FORM APPROVED

Budget Bureau No 1004-0135

Expires March 31 1993

SUNDRY NOTICES AND REPORTS ON WELLS O NOT USE this form for proposals to drill for to deepen or reentry to a different reservoir. USE "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE Type of Well West Oner WIW Name of Operator R. Well Name and Turner TA: #11 9 API Well Name and Turner TA: #11 9 API Well Name and Turner TA: #11 9 API Well Name and Turner TA: #11 10 Field and Peol. Grayburg-Jack 10 Field and Peol. Grayburg-Jack 11 Country or Farr Eddy Country, N CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion Notice of Intent Abandonment Recompletion New Construction Grayburg-Back Other Add Perforations Other Add Perforations Other Add Perforations Orkover existing water injection well as follows: Selectively perforate the interval 2650' - 3441'(OA). I hereby certify that the foregoing is true and correct Randy Jackson	on and Serial No.		
Submit in triplicate	LC-029395A		
Type of Well	ee or Tribe Name		
Subsequent Report Subs			
Name of Operator Swell Name and Operator Swell Name and Operator Swell Name and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611 9, API Well No. 30-015-05215 10, Field and Peol, Grayburg-Jack 11, Country or Par Eddy County, No. 12, Country or Par Eddy County, No. 13, Country or Par Eddy County, No. 14, Country or Par Eddy County, No. 14, Country or Par Eddy County, No. 15, Count	Agreement Designation		
Name of Operator DEVON EMERGY CORPORATION (NEVADA) Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (408) 235-3611 9. API Well No. 30-015-05215 10. Field and Pool. 660' FSL & 660' FEL of Section 18-T17S-R31E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF SUBMISSION Notice of Intent Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Casing Repair Abtening Casing Other Add Perforations Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).			
Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (408) 235-3611 Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FSL & 660' FEL of Section 18-T17S-R31E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF SUBMISSION Notice of Intent Abandonment Recompletion Now Construction Subsequent Report Plugging Back Non-Routine Fra Altering Casing Other Add Perforations Ot			
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611 30-015-05215 10. Field and Pool, Grayburg-Jack 11. County of Para Eddy County, N CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION Notice of Intent Abandonment Recompletion Subsequent Report Plugging Back Other Add Perforations Other Add Pe			
Location of Well (Footage. Sec., T., R., M., or Survey Description) 660' FSL & 660' FEL of Section 18-T17S-R31E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION Notice of Intent Abandonment Recompletion Non-Routine Fra Casing Repair Locations and measured and true vertical depths for all markers and zones pertinent to this work. ** Orkover existing water injection well as follows: Selectively perforate the interval 2650' - 3441'(OA). Inject through perforations strue and correct			
660' FSL & 660' FEL of Section 18-T17S-R31E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF SUBMISSION Notice of Intent Abandonment Recompletion Plugging Back Non-Routine Fra Altering Casing Other Add Perforations O	or Exploratory Area		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion New Construction Subsequent Report Plugging Back Casing Repair Altering Casing Conversion to Inj Dispose Water Other Add Perforations Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).	-		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHE TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Recompletion New Construction New Construction New Construction Non-Routine Fra Casing Repair Altering Casing Other Add Perforations Other Add Perforations Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is divided to starting and true vertical depths for all markers and zones pertinent to this work.)* Torkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).			
Notice of Intent Abandonment Change of Plans	νM		
Notice of Intent Abandonment Change of Plans			
Notice of Intent Abandonment Recompletion New Construction New Construction Non-Routine Fra Casing Repair Altering Casing Other Add Perforations Other Add Perforatio	ER DATA		
Subsequent Report Plugging Back Non-Routine Fra Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Importance Other Add Perforations Other Add Perforations Other Add Perforations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directions and measured and true vertical depths for all markers and zones pertinent to this work.)* Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).			
Subsequent Report Plugging Back Non-Routine Fra Casing Repair Water Shut-Off Conversion to Inj Other Add Perforations Other Recomplete Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directions and measured and true vertical depths for all markers and zones pertinent to this work.)* Orkover existing water injection well as follows: Selectively perforate the interval 2650' - 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650' - 3441'(OA). Inject through perforations 2650' - 3441'(OA).			
Final Abandonment Notice Casing Repair	·		
Altering Casing Other Add Perforations Other Recompleton or Rec	cturnig		
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directions and measured and true vertical depths for all markers and zones pertinent to this work.)* Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8''(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).	jection		
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directions and measured and true vertical depths for all markers and zones pertinent to this work.)* Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).	•		
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directions and measured and true vertical depths for all markers and zones pertinent to this work.)* Orkover existing water injection well as follows: Selectively perforate the interval 2650'- 3441'(OA). RIH with Baker AD-1 packer on 2 3/8"(IPC) tubing and set at ±2600'. Inject through perforations 2650'- 3441'(OA).	n Report and Log form)		
			
ned District Engineer Date 5/7/96			
is space for Federal of State office use)			
proved by ONIS SED I OF G. LARA Title PETROL SIM FIGH SEB ate 6/3 additions of approval, if any:	101		