		$G_{\bullet}(G_{\bullet}) = \bigcup_{i \in I} G_{i}$					
Form 9-331 (May 1963)	ITED STATES SUBMIT DEPARTMENT OF THE INTERIOR Of ther 1 verse side			14	Form a Budget 5. LEASE DESIGN		
	GE	OLOGICAL SURVEY		my 19	LC 02054		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)							
	GAS OTHER	<b>*</b> .	,	<i>*</i>	7. UNIT AGREEM		
2. NAME OF OPER	ATOR			<del></del> -	R TARM OR INA		

	m 9-331 ay 1963)	ITED STATES SUBMIT IN T. ICATE®			Form approved. Budget Bureau No. 42-R1424.		
	DEPARTM	MENT OF THE INTERIOF	(Other instructions on reverse side)	5. LEASE DESIGNATION			
	G	GEOLOGICAL SURVEY			LC 029548-A		
		CES AND REPORTS ON als to drill or to deepen or plug back TION FOR PERMIT—" for such propor		6. IF INDIAN, ALLOTTE	OR TRIBE NAME		
1.	OIL GAS OTHER	*		7. UNIT AGREEMENT NA	MB		
2.	NAME OF OPERATOR	Sinclair Oil & Gas Company			8. FARM OR LEASE NAME		
	Sinclair O	C. A. Russell					
3.	P. O. Box	1920, Hobbs, New Mexic	o 88240	9. WELL NO.			
4.	See also space 17 below.) At surface	from North line and 1384' from East line of					
	990' from North line a Section 18-T17S-R31E						
	Section 18-11/5-RJIE			18-T17S-R31E			
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, RT,	GR, etc.)	12. COUNTY OR PARISH	18. STATE		
		3763 DF		Eddy	New Mexico		
16.	Check An	propriate Box To Indicate Natu	us of Notice Report or C	Johns Data			

SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CARING SHOOT OR ACIDIZE ABANDON\* SHOOTING OR ACIDIZING ABANDONMENT\* REPAIR WELL CHANGE PLANS (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Convert oilwell to WIW

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

Reference New Mexico Oil Conservation Commission Order No. R-3185 granting approval of "Sinclair Russell Grayburg-Jackson Waterflood Project".

Convert oilwell to water injection well as follows: PROPOSE TO:

> Cleanout and set Guiberson Shorty Tension packer @ 3134' and inject water down 2-3/8"OD tubing into open hole 3209-3535'. Fill tubing casing annulus with corrosion inhibited fluid.

APRO OCH MEXICO

S. GEOVANEW MEXICO

- API DATE

- API 18. I hereby certify that the foregoing is true and correct Engineer TITLE (This space for Federal or State APPROVED BY

\*See Instructions on Reverse Side Orig&4cc: USGS, Artesia

cc: Regional Office

cc: file