

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR. ICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sinclair Oil & Gas Company		8. FARM OR LEASE NAME Turner "A"	
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240		9. WELL NO. 15	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1650' fr the North line and 1980' fr the West line		10. FIELD AND POOL, OR WILDCAT Grayburg Jackson	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 19-T17S-R31E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3658' GR		12. COUNTY OR PARISH Eddy	
		18. STATE New Mexico	

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other) Convert oilwell to WIW	<input checked="" type="checkbox"/>		

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

T.D. Drilled 3442'. PBSD 3045'. Presently producing from Grayburg Jackson Open Hole 2910-3045' 6 BOPD and 0 BWPD.

PROPOSE TO: Drill out to total depth 3442'. Run 2-3/8"OD tubing and packer set @ approx. 2835'. Convert from oilwell to water injection well in Grayburg Jackson Open Hole interval 2910-3442' in Russell-Turner Waterflood Area.

**RECEIVED**  
NOV 2 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Lee Hembree TITLE Engineer DATE 10-31-67

(This space for Federal or State office use)

APPROVED BY James A. Kraft TITLE \_\_\_\_\_ DATE NOV 2 1967  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side Orig&4cc: USGS, Artesia, N.M.  
cc: Regional Office  
cc: file