Form 9-331 (May 1963)

16.

## TITED STATES DEPARTALINT OF THE INTERIOR (Other instruction verse side)

SUBMIT IN T ICATE\*

Budget Bureau No. 42-R1424.

LC 031844

GEOLOGICAL SURVEY

SUNDRY NOTIC	es and	REPORTS	ON	WELLS
--------------	--------	---------	----	-------

	SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir,  Use "APPLICATION FOR PERMIT" for such proposals.)	G. IF INDIAN, ALLOTTEE	OR TRIBE NAME
	OIL X GAS WELL OTHER	7. UNIT AGREEMENT NA	A E
2.	Atlantic Richfield Company  DEC 5 1974	8. FARM OR LEASE NAM Fren Oil Co.	
3.	P. O. Box 1710, Hobbs, New Mexico 88240 C.C.  LOCATION OF WELL (Report Location clearly and in accordance with any State year). C.F.	9. WELL NO.	
١.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below.)  At surface	10. FIELD AND POOL, OR Fren Seven Ri	
	660' FSL & 660' FEL (Unit letter P)	11. SEC., T., R., M., OR B. SURVEY OR AREA	LK, AND
4	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	19-17S-31E  12. COUNTY OR PARISH	13. STATE
	3592 <b>'</b> GR	Eddy	N M

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	[
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other) Temporarily Aba		x
(Other)				(Note: Report results of mul Completion or Recompletion R	tiple completion on Welleport and Log form.)	i

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

The above well was temporarily abandoned during the month of August, 1971. The well was shut in because it was uneconomical to produce. This well is a secondary recovery prospect after deeper waterflood is completed in 8 to 10 years.



TITLE Dist. Prod. & Drlg. Supt.	DATE October 31, 1974
TITLE WELL MUST	DATE
THER APPROVED. THE STATE OF PLUGGED BY	
์ คี <b>ดีก</b> าร - 1975	
*See Instructions on Reverse Side	
	TITLE WELL MUST  STHER APPROVED. WELL MUST  SENSE OF PLUGGED BY  SENSE OF 1975  *See Instructions on Reverse Side