

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM OIL CONS. COMMISSION
SUBMIT IN TRIPL
Drawings DD (Other Instructions)
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-1
Expires August 31, 1985

dsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL LC 029395 (b)
2. NAME OF OPERATOR ARCO OIL AND GAS COMPANY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1610 Midland, Texas 79707	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 760' FSL & 330' FEL (Unit P)	8. FARM OR LEASE NAME Turner "B"
	9. WELL NO. 20
	10. FIELD AND POOL, OR WILDCAT Fren Seven Rivers
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 20-17S-31E
14. PERMIT NO API #30-15-05292	12. COUNTY OR PARISH Eddy
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3751 GR	13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-19-86 RUPU. P&A as follows:

Plug	Cmt.	Interval
1	114sx 'H' neat	1400-1996
2	150sx 'H' neat	1156-1300. Perf @ 1300'. CR @ 1176' w/20' cmt on top.
3	230sx 'H' neat	0-560. Perf @ 560.

Installed dry hole marker. Well P&A'd 6-20-86

MIRU PU. NU BOP. WIH w/Guib Univ VI pkr on 2-7/8" N-80 WS. Sat down @ 1308'. Pmpd 50 bbls FW down ann. FIH & set pkr @ 1996'. PA to 500 psi. Bled to 0 psi in 2 mins. Est PIR into Seven Rivers OH 2075-2184' w/2 BPM @ 1600 psi. POH w/pkr WIH w/CR on 2-7/8" WS & set @ 1996'. Estd PIR down 2-7/8" tbg w/comm out 2-7/8" x 7" ann. PUH w/stinger to 1058'. SION.

POH w/stinger. WIH w/OE 2-7/8" WS to 1996'. Spot'd 114 sx C1 "H" NEAT f/1996-1400'. PUH to 1361'. RO tbg. POH. Perf'd 4 - 0.43" holes @ 1300'. WIH w/Guib Univ VI pkr on 2-7/8" WS & set @ 1176'. PA to 500 psi. Estd PIE into sqz holes @ 1300' w/2 BPM @ 900 psi w/no rtns on 7" X 8-5/8" ann. WIH w/CR on 2-7/8" WS & set @ 1176'. PA to 500 psi. Sqz'd holes @ 1300' w/150 sx C1 "H" NEAT. SP 600 psi. Dmpd 20' cmt on CR @ 1176'. POH. LD WS. Perf'd 4 - 0.43" holes @ 560'. Pmpd down 7" csg. Unable to est circ out 7" X 8-5/8" ann. Sqz'd holes @ 560' w/230 sx C1 "H" NEAT down 7" csg. No circ out 7" X 8-5/8" ann. ND BOP. Well P&A'd 6/20/86. Cut off WH. Installed dry hole marker.

Best FD-2
8-1-86
P&A

18. I hereby certify that the foregoing is true and correct
SIGNED Ken W. Gosnell TITLE Engr. Tech. Spec. DATE 7-10-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side