Form 9-331 (May 1963)	M. M. O ITED STATES DEPARTMENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN T ICATE* (Other instructions on re- lor verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. LC 029395 (b)
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. T.A. OIL X GAS WELL WELL OTHER 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME
Atlantic Richfield Company			8. FARM OR LEASE NAME Turner "B"
P. O. Box 1978, Roswell, New Mexico 88201			9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL, 1650' FEL (Unit letter B)			10. FIELD AND FOOL, OR WILDCAT Fren-7 Rivers 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T17S, R31E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF 3678 DF	· · · · · · · · · · · · · · · · · · ·	12. COUNTY OR PARISH 13. STATE Eddy N.M.
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR	MULTIPLE COMPLETE ABANDON* CHANGE PLANS COMPLETED OPERATIONS (Clearly state all pertinent well is directionally drilled, give subsurface located by the subsurface located	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Temporari (Note: Report results of Completion or Recomple	REPAIRING WELL ALTERING CASING ABANDONMENT* Y Abandon Y Multiple completion on Well tion Report and Log form.)
tubir	well has been temporaril ng and capping well w/200 73. Will hold well for w	0# WOG valve. Wel	

18. I hereby certify that the foregoing is true and correct

SIGNED A Little Dist. Drlg. Supervisor

(This space for Federal or State office use)

APPROVED BY LEAD TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACTIVE DISTRICT ASSESSMENTS