

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TYPE
(Other instructions
on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

16 0291420 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Shelly Unit

8. FARM OR LEASE NAME

Shelly Unit

9. WELL NO.

64

10. FIELD AND POOL, OR WILDCAT

Grayburg-Jackson

11. SEC. T. R. M. OR BLK. AND
SURVEY OR AREA

Sec. 21-17N-31E

12. COUNTY OR PARISH 13. STATE

Hddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

SEKILLY OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 730 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2080' FNL & 710' FNL Sec. 21-17N-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3835'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Perforate and Treat

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Moved in and rigged up Workover Rig.
2. Pulled rods and tubing.
3. Perforated 4-1/2" OD casing with one shot per interval at the following depths: 3038', 3066', 3070', 3083', 3116', 3128', 3164', 3180', 3197', 3228', 3230', 3266', 3277', 3297', 3311', 3326', 3337', 3381', 3389', 3398', 3450', 3455' and 3483', a total of 23 shots.
4. Isolated and treated through 4-1/2" OD casing 3038-3483' with 1900 gallons 15% regular acid and 46 ball sealers.
5. Isolated and treated through 4-1/2" OD casing 3038-3483' with 25,000 gallons water and 25,000# 20/40 sand and 14 ball sealers.
6. Pull retrievable bridge plug and run rods and tubing.
7. Pumped 41 barrels oil in 24 hours and returned well to production status 12-4-67.

Workover operations commenced 12-2-67.

Well completed 12-3-67.

18. I hereby certify that the foregoing is true and correct

SIGNED W. S. B. 12/3/67TITLE District SuperintendentDATE December 7, 1967

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
DEC 8 1967
U.S. GEOLOGICAL SURVEY
ARTESIA, N.M.APPROVED
DEC - 8 1967
R. L. DEAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.