Form 3160-5 (JUNE 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reen ry to a different reservoir Use "APPLICATION FOR PERMIT -" for such proposals			5. Lease Designation and Serial No.	
			6. If Indian, Allotte or Tribe Name	
	Use APPLICATIO	N POR PERMIT - 101 such proposals		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation	
1. Type of Well	Oil Well Gas Well	Other X Water Injection	Skelly Unit	
2. Name of Opera		Ollici A water injection	8. Well Name and No.	
The Wiser Oil Company			66	
3. Address and Telephone No.			9. Well API No.	
			30-015-05341	
8115 Preston Road, Suite 400, Dallas, TX 75225 (214)265-0080			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Gravburg Jackson 7-Rivers-QN-GB-SA 11. County or Parish, State	
Unit H, 2080' FNL & 710' FEL. Sec 21, T17S, R31E			Eddy Loo-New Mexico	
12.		e Nature of Notice, Report, or Other Data		
	TYPE OF SUBMISSION	Т	YPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans	
	Notice of Intell	Recompletion	New Construction	
	X Subsequent Report	Dhaming Bark	Non-Routine Fracturing	
	A Suisequent Report	Casing Repair	Water Shut-Off	
	Final Mandanm at Vation	Altering Casing	Conversion to Injection	
	Final Abandonment Notice	X Other	Dispose Water	
		Return SI to njection	Dispose water	
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form).	
13. Describe Proposed	d or Completed Operations (Clearly state all pertine	ent details, and give pertinent dates, including estimated da	te of starting any proposed work. If well is directionally drilled, give	
	ons and measured and true vertical depths for all ma		Post ID-3	
04/21/97	7 MIRU Lucky WS #13. Flwd wel	I dn. Attempted to remove WII & slips wino succe	8-1-97	
04/22/97		ompleted Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give it measured and true vertical depths for all markers and zones pertinent to his zone? MIRU Lucky WS #13. Flwd well din. Attempted to remove WH & slips wino success. Removed WH & slips to repair esg leak. Installed WH & BOP. Unset pkr. POH & tally tbg. RIH w 3-7/8" bit on on 2-3 8" tbg. CO fill f 3046'-3100'. Csg. leak a bradenhead. POH witbg & bit.		
04/23/97	ND BOP & removed WH. RU Bowen spear & 1 jt 2-7 8" thg. Work esg. Cut off bad esg. Weld on bell nip. Install WH. NU BOP. RIH w notched collar on 2-3 8" thg. CO fill f 3100'-3550'. Circ. POH w notched collar. RIH w 3-7 8" bit to 3550'. POH w bit. RIH w 4-1 2" Howeo CIBP on 2-3 8" thg. Set CIBP @ 3515. Pld to 3500'. Sptd 300 gals xylene.			
04/24/97	4-1 2" esg f 3162',63', 65'-67', 94' on 2-3 8" Duo-lined thg. NU BO	LD 2-3 8" thg & set tool. RU HLS & attempted perf. No collars located. Dmpd 2 sks cmt on rtnr. Ran GR-CCL f'3480'-2500'. Perfd 4-1 2" csg f'3162'.63', 65'-67', 94'-96', 98', 3298', 3310', 12', 38', 41', 42', 86'-88', 97', & 99' (20 holes). RHI w/4-1/2" Baker AD-1 pkr on 2-3 8" Duo-lined thg. NU BOP. Installed WH. Pmpd f kr fl. Set pkr \hat{q} 2978'. Tstd csg to 300". Held OK. Acidized perfs. w 3500 gals 15% Fer-check acid & 2000" rock salt. ATF 2710" \hat{q} 3.9 bpm. MTP 3597" \hat{q} 6.1 bpm. ISIP 1781", 5 min. 1734". 10 min. 1708" 15 min. 1684".		
04/28/97	7 Initial injection rate 300 BWPD /	ř 600#.		
	at the foregoing is true and correct			
Signed:	Such Styr	Title Agent	Date 07/08/97	
(THIS SPACE FOR FEDI	ERAL OR STATE OFFICE USE)			
Approved By:		Tule	Date	
Conditions of approval	l, if any		1 10	

Title 18 U. S. C. Section 1001, makes it a crime for any person knowingly and willfully to make any department of agency of the United States any false, ficticious or fraudulent statments or representations as to any matter within its jurisdiction