5-USAS-ARTESIA

1-R.J. STARRAK-15TH FLOOR LSA

CA DV-MTDT AND

Form	9-331	
	1963)	

T-W.D.	CMILL	LITINIMATAT
Form 9-331		

I-W.D.	CKKI-LITDHWIND
Form 9 .221	

I-W.D.	CWEL-LITDIUMO
Form 0 .221	

UNITE	ED S	TAT	<u> </u>	
DEPARTMENT	OF	THE	INTERIOR	

SUBMIT IN TRIPLICATE\*
(Other instructions on re-(Other in verse side)

Form approved, Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1-FILE

14. PERMIT NO.

16.

GEOLOGICAL SURVEY

LC-029418 (A)

SUNDRY	NOTICES	AND	REPORTS ON WELLS
	•		difforant recepçoir

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoi Use "APPLICATION FOR PERMIT-" for such proposals.)

REBEIVED INJECTION WELL GAS WELL OTHER 2. NAME OF OPERATOR GETTY OIL COMPANY -3. ADDRESS OF OPERATOR

P. O. BOX 730, HOBBS, NEW MEXICO 88240

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) TESIA, OFFICE At surface

Unit D, 660; FNL and 660' FWL

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3863' D.F.

8. FARM OR LEASE NAME 9. WELL NO.

7. UNIT AGREEMENT NAME

SKELLY UNIT

40 10. FIELD AND POOL, OR WILDCAT

GRAYBURG-JACKSON 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC.23-17S-31E

12. COUNTY OR PARISH | 13. STATE N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL	NO	MICE OF INTENTION TO:	1	SUBSEQUENT REPORT OF:	
FRACTURE TREAT  MULTIPLE COMPLETE  SHOOT OR ACIDIZE  SHOOTING OR ACIDIZING  ABANDON*  (Other)  SHOOTING OR ACIDIZING  ABANDONMENT*  (Other) BRING UP CEMENT TOP  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		FRACTURE THEATMENT ALTERING CASING SHOOTING OR ACIDIZING ABANDONMENT*  (Other) BRING UP CEMENT TOP	, I

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Pulled tubing and packer.

Ran cement Bond Log.

Found Top of Cement at 2520'.

Perforated 7" casing @ 2510. Squeezed perforations w/400 sxs. Howco-Lite and 100 Sxs. of Class "C".

Ran Temperature Survey and found Cement top @ 1700'.

Drilled out cement and tested casing to 800#. for 15 min. O:K.

Cleaned out 4-1/2" liner from 3821 to 3827'.

Reran packer and tubing.

Placed well on injection.

RECEIVED

7 1978

U. ARTESIA, NEW MEXICO

SIGNED DALE R. CROCKETT	TITLE AREA SUPERINTENDENT	DATE	2-7-78
(This space for Federal or State office us)	TITLE ACTING DISTRICT ENGINEER	DATE	FEB 9 - 1978