

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TF
(Other instruct
verse side)

ICATE*
on - re

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back in a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 029418 - b	
2. NAME OF OPERATOR Shelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME ..	
3. ADDRESS OF OPERATOR Box 730 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME Shelly Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1900' FNL & 460' FNL Section 23-178-31E		8. FARM OR LEASE NAME Shelly Unit	
14. PERMIT NO. -		9. WELL NO. 70	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3881' DF		10. FIELD AND POOL, OR WILDCAT Shelly Unit Jackson	
		11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec. 23-178-31E	
		12. COUNTY OR PARISH Hddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Perforate & Treat	X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Moved in and rigged up workover unit and pulled rods and tubing.
2. Perforated 4-1/2" OD Liner with one shot per interval at the following depths: 3288', 3312', 3319', 3354', 3368', 3385', 3389', 3394', 3411', 3429', 3439', 3479', 3495', 3504', 3512', 3525', 3542', 3555', 3569', 3579', 3596', 3620', 3629', 3649', 3660', 3691', 3701', a total of 27 shots.
3. Treated perforations 3288-3701' with 1500 gallons 15% acid.
4. Treated perforations 3288-3701' with 30000 gallons treated water and 30000# 20/40 sand.
5. Ran rods and tubing.
6. Pumped and tested. Well pumped 12 barrels oil and 5 barrels water in 24 hours.

18. I hereby certify that the foregoing is true and correct

SIGNED **V. E. Fletcher**

TITLE **District Superintendent**

DATE **September 1, 1967**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
SEP - 7 - 1967
R. L. DEERMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

APPROVED