

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

LAND CONSERVATION COMMISSION
ALBUQUERQUE, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mack Energy Corporation

3. Address and Telephone No.

P.O. Box 1359, Artesia, NM 88211-1359 (505) 748-1288

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310 FNL 2308 FWL Sec 22-T17S-R30E

5. Lease Designation and Serial No.

NM-0467930

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sinclair Parke Fed #1

9. API Well No.

30-015-10334

10. Field and Pool, or Exploratory Area

Jackson Abo

11. County or Parish, State

Eddy, New Mexico

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 9-1-93 Rigged up. Ran in hole w/CIBP set @ 6093' and dump 60' cmt on top plug. Set CIBP @ 5204' w/35' cmt on top. Perfed csg # 5144' and 4550'. Ran in hole w/SV Retainer and set @ 5108', pump 150sx Class C cmt thru perfs 5144', circ cmt thru perfs 4550', pull tbgt to 4500' and circ 35sx cmt to surface.
- 9-7-93 Drilled out cmt from 4529' to 4761' and clean out to PBTD 5108'. Perf csg @ 4799, 4802, 15, 33, 37, 42, 65, 66, 85, 91'.
- 9-8-93 Acidized perfs w/1,500 gals 15% NE acid. Swab test all wtr.
- 9-9-93 Perfed csg 4573-5040'. Acidized perfs 4952-5040' w/ 1,000 gals 15% NE acid. Swab all wtr.
- 9-10-93 Acidized perfs 4573-4664' w/1,000 gals 15% NEFE acid.
- 9-13-93 Ran in hole w/SV Retainer and set @ 4300' and squeeze all perfs w/200sx Class C cmt. PBTD 4700'.
- 10-5-93 Drill out cmt and cmt retainer and CIBP @ 6093' and clean out to PBTD 6972'.
- 10-6-93 Set CIBP @ 6950' w/35' cmt on top. Perfed csg @ 6765-75'. Acidized perfs w/1,000 gals 15% NE acid.

CONTINUED ON BACK

14. I hereby certify that the foregoing is true and correct

Signed David D. Carter Title Production Clerk

Date 10-27-93

(This space for Bureau of Land Office use)

Approved by David R. Glass Title _____

Date _____

Conditions of approval, if any:

1993

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

10-7-93 Acidized perfs 6765-75' w/32,000 gals 20% NE and 54,000 gals gel water.

10-9-93 Put well on pump.