

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE MANNER INDICATED*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water injection well		5. LEASE DESIGNATION AND SERIAL NO. 10-12322(1)
2. NAME OF OPERATOR Amador Petroleum Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 200, Artesia, N.M.		7. UNIT AGREEMENT NAME Graybar-Jackson Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1910' T&L & 600' T&L Sec. 22 SW, SW Sec. 22 T17-S 139-1		8. FARM OR LEASE NAME Tract 5
14. PERMIT NO. R-2323	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,805'	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Graybar-Jackson
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22-17-S 139-1
		12. COUNTY OR PARISH Adair
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) **Plug back & re-perforate** ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

a 4" Baker cast lead drillable bridge plug was set in 4 1/2" casing at 3,100'. Present tested bridge plug at 3,500' and plug holding. Perforate with Abrasi Jet method at 3,112', 3,114', 3,116', 3,118', 3,120' two holes per ft. Commenced water injection into perforations 3,112' - 3,120'.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles HaggardTITLE Production EngineerDATE May 23, 1967

(This space for signature or stamp use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED
MAY 26 1967
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED
MAY 25 1967
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.