

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DUPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028992(J)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well	7. UNIT AGREEMENT NAME Grayburg Jackson Unit
2. NAME OF OPERATOR Anadarko Production Company	8. FARM OR LEASE NAME Tract No. 5
3. ADDRESS OF OPERATOR Box 116 Loco Hills, New Mexico	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FWL & 660' FSL Sec. 22, T 17 S, R 30 E, Eddy County, New Mexico	10. FIELD AND POOL, OR WILDCAT Grayburg Jackson
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA N4EPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3625 GL	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐**Squeeze and Re-perforate**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled out bridge plug and cleaned well out to 3185'. Ran 2" tubing with packer set at 2478' - cemented with 200 sx Class C cement with 1lb Flocale/sk and 2% CaCl₂ spotted cement and squeezed at 3500 psi. Shut well in 36 hours, pulled tubing and packer, ran tubing with 3 7/8" bit - found cement top at 2750' - drilled solid cement to 3150' - tested with 2000 psi pressure. Pulled tubing & bit and ran tubing with abrasijet tool - perforated from 3112-20 @ 2holes/ft. Spotted 250 gal 15% Hcl across perforations and pumped into formation .4 Bpm at 1500 psi. Hooked well up and returned to water injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. LaytonTITLE **District Superintendent**DATE **13 December 1967**

(This space for Federal or State office use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

DEC 14 1967

U. S. GEOLOGICAL SURVEY

APPROVED

DEC 14 1967
R. L. GLENN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.