

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

B 9563, B 10714, B 1266, B 255, B 514

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name G-J West Coop. Unit
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name
3. Address of Operator Box 1031, Midland, Texas 79701	9. Well No. 29
4. Location of Well UNIT LETTER I, 660 FEET FROM THE east LINE AND 2130 FEET FROM THE south LINE, SECTION 21 TOWNSHIP 17-S RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Grayburg-Jackson
15. Elevation (Show whether DF, RT, GR, etc.) 3563 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUS AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUS AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROCEDURE:

1. Pull rods & tubing. Move off pulling unit.
2. Perforate zones of interest w/one 3/8" jet per interval:
Lovington Sand, 2562, 2527, 2522 Anderson Zone 3, 2324, 2321
Premier Sand, 2406, 2401, 2395, 2390 Anderson Zone 2, 2309
Anderson Zone 6, 2375 Anderson Zone 1, 2293, 2289, 2284
Anderson Zone 5, 2361, 2357 Metex Zone 2, 2264, 2253
Anderson Zone 4, 2347, 2343
- Set retrievable bridge plug & wire line between Oolitic & Lovington Zones.
3. Frac down csg. w/50,000 gals. gelled water & 75,000# 20-40 sand. Overflush w/10 BW.
4. Shut-in a minimum of 12 hrs.
5. Bleed off pressure, run tbg. w/retrievable head & recover bridge plug.
6. Run tbg. & rods and put on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. F. Carnes J. F. Carnes TITLE District Production Foreman DATE 7-3-67

APPROVED BY W. A. Gressett TITLE Oil and Gas Supervisor DATE 7-3-67

CONDITIONS OF APPROVAL, IF ANY: