HO. OF COPIES RECEIVED	Supersedes Old
DISTRIBUTION	C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	5a. Indicate Type of Lease
U.S.G.S.	State X Fee.
LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR /	B-1266
AND DESCRIPTION OF THE PROPERTY OF WELL C	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR POPOSALS TO BRILL OR TO BEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAB WELL WELL WHER.	G-J West Coop. Ut.
, Name of Operator	8. Farm or Lease Name
Tenneco Oil Co.	G-J West Coop. Ut.
, Address of Operator	9. Well No. 32
P. O. Box 1031, Midland, Texas	
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER 1980 FEET FROM THE East 1980 FEET FROM	Grayburg-Jackson
00 Engt	
THE South LINE, SECTION 21 TOWNSHIP 17 South RANGE 29 East NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
15, Elevation (Jnow whether DI, III, OK, every	Eddy
16. De la Languagia Des To Indiana Natura of Nation Papart of Oth	
Check Appropriate Box 10 indicate Nature of Notice, Report of Oth	er Data
NOTICE OF INTENTION TO:	REFORT OF:
PLUS AND ABANDON REMEDIAL WORK	ALTERING CASING
The same of the sa	PLUG AND ABANDONMENT
The second secon	FEGG AND ADAMSON
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	
Perf & treat additional pay	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE'I fos.	
Propose to:	
1. Pull rods, pump & tubing.	
2. Perforate Premier zone with one 1/2" hole at following depths:	
2397, 2399, 2401, 2403, 2409, 2410, 2411, & 2412.	
3. Set retrievable bridge plug below above perfs.	
4. Spot 250 gals mud acid across perfs. 5. Frac perfs with 20,000 gals. gelled water & 30,000# 20-40 mesh sa	and.
5. Frac perfs with 20,000 gals. gelled water & 30,000# 20-40 mesh se	
6. Retrieve bridge plug. 7. Run tubing pump & rods & commence pumping.	REGET
7. Run tubing pump & rods & commence pumping. 8. Producing interval will be the above perfs 2397-2412, plus the or	iginal
perfs in Oolitic zone 2589-2690.	DEC 1
peris in odlitic zone 2)09-2090:	17-1
	ARTECIAL DESIGNATION
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
	Dec. 12 1066
J. F. Carnes Dist. Prod. Eng.	Dec. 13, 1966
A SE NUM DAD INSDICTOR	
APPROVED BY W. a. Gressett TITLE OIL AND GAS !NSPIGTOR	DATE DEC 1 1966