

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B 1266,	

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company ✓	8. Farm or Lease Name G-J West Coop. Unit
3. Address of Operator Box 1031, Midland, Texas 79701	9. Well No. 37
4. Location of Well UNIT LETTER G, 1980 FEET FROM THE east LINE AND 1980 FEET FROM THE north LINE, SECTION 21, TOWNSHIP 17-S, RANGE 29-E NMPM.	10. Field and Pool, or Wildcat Grayburg-Jackson
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROCEDURE:

1. Pulled rods and tubing. Moved off pulling unit.
2. Perforated at 2266' - 2557' w/20 3/8" jets. *
Set retrievable bridge plug and wire line at 2575'.
3. Frac down csg. w/500 gals acid and 50,000 cals. gelled water and 75,000# 20-40 sand and 6 perforation sealers. Overflushed w/10 BW.
4. Shut-in over night.
5. Bled off pressure, ran tbg. w/retrievable head and recovered bridge plug.
6. Ran tbg. and rods and put on pump.

* 1 hole at each of the following intervals 2266, 78, 95, 2301, 18, 28, 33, 55, 60, 74, 98
2402, 05, 68, 11, 2519, 25, 38, 48 + 2557

RECEIVED

200 10 1967

LAND OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. F. Carnes TITLE District Production Engineer DATE 7-6-67

APPROVED BY W. A. Gressett

TITLE W. A. Gressett

DATE 7-6-67

CONDITIONS OF APPROVAL, IF ANY:

