

UNITED STATES
DEPARTMENT OF
BUREAU OF LAND MANAGEMENT

Submit in triplicate
DATE

Expires August 31, 1985

45F

5. LEASE DESIGNATION AND SERIAL NO.

LC055958

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED BY

MAR 18 1986

O. C. D.

ARTESIA, OFFICE

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Water Injection Well
2. NAME OF OPERATOR
Burnett Oil Co., Inc.
3. ADDRESS OF OPERATOR
1500 InterFirst Tower, Fort Worth, TX 76102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

Unit D, 660' FNL, 660' FWL, Sec. 13, T17S, R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether LF, RF, GR, etc.)

3727 GR

7. UNIT AGREEMENT NAME

Grayburg Jackson (San Andres)

8. FIRM OR LEASE NAME

GJ:AU

9. WELL NO.

32

10. FIELD AND POOL, OR WILDCAT

GB/SA G. Jackson - SR-S-G-SA-

11. SEC., T., R., E., N., OR BLE. AND SURVEY OR AREA

13-T17S-R30E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well has recently undergone extensive remedial work to shut off a low volume casing water leak. Repairs were not successful due to weak casing. We now propose to plug and abandon this well as follows:

- (1) Set CIBP @ ±3232' with 35' cement on top.
- (2) Set cement retainer @ 2260'. Squeeze Red Sand with 200 sks.
- (3) Spot continuous cement plug 2260'-1800'.
- (4) ~~Spot 40' cement plug 560'-520'.~~
- (5) Spot 50' cement plug at surface with 4" marker. (Both sides csg.)
- (6) Reclaim location.

4. Perf at 1300' (Base salt)
100' plug both sides csg.

Perf at 441' (Top salt)
circ cmt, or 100' plug

18. I, the undersigned, hereby certify that the foregoing is true and correct

SIGNATURE *John E. McPherson* TITLE Production Superintendent

DATE 2/26/86

(Leave space for Federal or State office use)

APPROVED BY *Scott Adams* TITLE *Asst. Dir.*
DATE 3-1-86

DATE 3-1-86

Subject to
Like Approval
by State

*See Instructions on Reverse Side