Form 3160-5 (June 1990)

UNITED STATES DEPARTML OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

o not use this form for proposals to drill o	or to deepen or reentry to a different reservoid OR PERMIT—" for such proposals	/ED 5. Lease Designation and Serial No. LC-029395A
USE AFFLICATION FO	ON FERMIT— TOT SUCH Proposals	6. If Indian, Allottee or Tribe Name
SUBMIT	IN TRIPLICATE	H 12. 02
		7. If Unit or CA, Agreement Designation
Type of Well ☐ Oil ☐ Gas Well ☐ Well ☐ Well ☐ Other ☐ WIW	्राः वि पञ्जाति ।	
770H	ROSWELL O	O Woll Now - 1 N
Name of Operator DEVON ENERGY CORPORATION (NEV.)	ana) JUN - 6 1997	8. Well Name and No.
	ADA)	Turner "A" #35
Address and Telephone No.	75 G M - 175 J W 14 J F T	9. API Well No.
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611 Location of Well (Footage, Sec., T., R., M., or Survey Description) 1800' FNL & 660' FEL of Section 19-T17S-R31E		30-015-20097
		10. Field and Pool, or Exploratory Area
		Grayburg Jackson
		11. County or Parish, State
		Eddy County, NM
CHECK APPROPRIATE BOXY	TO MIDIOATE MATERIAL	
) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF AC	TION
	Abandonment	Change of Plans
Notice of Intent		New Construction
	Recompletion	
	Plugging Back	■ Non-Routine Fracturing
Subsequent Report	☐ Plugging Back ☐ Casing Repair	☐ Water Shut-Off
•	☐ Plugging Back ☐ Casing Repair ☐ Altering Casing	Water Shut-Off Conversion to Injection
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Dettinent details, and give pertinent dates including estimated date of	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well
Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33 5/13/97 - Acidized perfs 28 5/15/97 to 5/17/97 - Found piece of 8 5/8" c 5/21/97 - Dumped 10 sxs ce	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of so for all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. ement down 4 1/2" x 8 5/8" annulus. TO & 2 3/8" IPC tubing. Set pkr @ 2617'.	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and the
Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33. 5/13/97 - Acidized perfs 28. 5/15/97 to 5/17/97 - Found piece of 8 5/8" of 5/21/97 - Dumped 10 sxs ce 5/22/97 - Ran AD-1 packer	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of so for all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. ement down 4 1/2" x 8 5/8" annulus. TO & 2 3/8" IPC tubing. Set pkr @ 2617'.	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and well are starting and well are well as the starting and well as the starting and well are well as the starting and well as the starting and well are well as the starting and the starting and well as the starting and the starting and well as the starting and well as the starting and well as the starting and the starti
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33: 5/13/97 - Acidized perfs 28: 5/15/97 to 5/17/97 - Found piece of 8 5/8" c 5/21/97 - Dumped 10 sxs ce: 5/22/97 - Ran AD-1 packer 5/24/97 - Back on injection.	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of sor all markers and zones pertinent to this work.)* One to this well: 30°. Set CIBP @ 3270°. Perf'd @ 2679°. 79°-3179° w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. To a 2 3/8" IPC tubing. Set pkr @ 2617°. CORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting and t
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33. 5/13/97 - Acidized perfs 28. 5/15/97 to 5/17/97 - Found piece of 8 5/8" of 5/21/97 - Dumped 10 sxs ce 5/22/97 - Ran AD-1 packer	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of so for all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. TO acid & 2 3/8" IPC tubing. Set pkr @ 2617'. CORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and well are starting and well are well as the starting and well as the starting and well are well as the starting and well as the starting and well are well as the starting and the starting and well as the starting and the starting and well as the starting and well as the starting and well as the starting and the starti
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33. 5/13/97 - Acidized perfs 28. 5/15/97 to 5/17/97 - Found piece of 8 5/8" of 5/21/97 - Dumped 10 sxs ce 5/22/97 - Ran AD-1 packer 5/24/97 - Back on injection.	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of sor all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. To acid & 2 3/8" IPC tubing. Set pkr @ 2617'. (ORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and well and well are the starting and the starting
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33: 5/13/97 - Acidized perfs 28: 5/15/97 to 5/17/97 - Found piece of 8 5/8" c 5/21/97 - Dumped 10 sxs ce: 5/22/97 - Ran AD-1 packer 5/24/97 - Back on injection.	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of so for all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. TO acid & 2 3/8" IPC tubing. Set pkr @ 2617'. CORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting any proposed work. If well is directionally drilled, give the starting and t
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33: 5/13/97 - Acidized perfs 28: 5/15/97 to 5/17/97 - Found piece of 8 5/8" c 5/21/97 - Dumped 10 sxs ce: 5/22/97 - Ran AD-1 packer 5/24/97 - Back on injection.	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of sor all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. To acid & 2 3/8" IPC tubing. Set pkr @ 2617'. (ORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and well and well are the starting and the starting
Subsequent Report Final Abandonment Notice Describe Proposed or Completed Operations (Clearly state all subsurface locations and measured and true vertical depths The following work was do 5/12/97 - Cleaned out to 33: 5/13/97 - Acidized perfs 28: 5/15/97 to 5/17/97 - Found piece of 8 5/8" c 5/21/97 - Dumped 10 sxs ce: 5/22/97 - Ran AD-1 packer 5/24/97 - Back on injection.	Plugging Back Casing Repair Altering Casing Other Added perfs & acidized Pertinent details, and give pertinent dates, including estimated date of sor all markers and zones pertinent to this work.)* One to this well: 30'. Set CIBP @ 3270'. Perf'd @ 2679'. 79'-3179' w/3000 gals 15% HCl acid + 4 hole in 8 5/8" casing. Cut off 8 5/8" @ 2 casing. The ement down 4 1/2" x 8 5/8" annulus. To acid & 2 3/8" IPC tubing. Set pkr @ 2617'. (ORIG. SO	Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) starting any proposed work. If well is directionally drilled, given the starting and proposed work. If well is directionally drilled, given the starting and well and well are the starting and the starting