

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN PLICATE\*  
(Other instructions on  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

LC 029395 A

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plug and Abandon	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Sinclair Oil & Gas Company	8. FARM OR LEASE NAME Turner "A" SP
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240 10-1-68	9. WELL NO. 37
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' fr the South line and 660' fr the West line	10. FIELD AND POOL, OR WILDCAT Wildcat - Cisco
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA 18-T17S-R31E	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

Plug ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Present Total Depth: 9800'. 13-3/8"OD casing set @ 403' and cemented w/400 sks. to surface. 8-5/8"OD casing set @ 3900' and cement w/2000 sks. Top of cement 240' fr surf.  
PROPOSE TO: Spot 50 sack cement plug 7000-7100', open hole.  
Spot 50 sack cement plug 5500-5600', open hole.  
Spot 50 sack cement plug 3850-3950', bottom of 8-5/8"OD casing.  
Spot 10 sack cement plug in 8-5/8"OD casing 20' - 0' surface.  
Install regulation dry hole marker, clean and level location. P&A.

SINCLAIR OIL CORPORATION

10-1-68

RECEIVED

JUL 11 1968

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Superintendent

DATE

7-11-68

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Orig&4cc: USGS, Artesia  
cc: Regional Office  
cc: file

\*See Instructions on Reverse Side

APPROVED

R. L. DEAN

ACTING DISTRICT