

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-055264

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection

OCT 16 1979

2. NAME OF OPERATOR

WINDFOHR OIL COMPANY

3. ADDRESS OF OPERATOR

Box #198, Artesia, New Mexico 88210

O. C. C.
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface 660' from north and 1980' from east lines,
Sec. 12-17S-30E

7. UNIT AGREEMENT NAME

Grayburg Jackson San Andres

8. FARM OR LEASE NAME

9. WELL NO.

46

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson G-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12-17S-30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3729 KB

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☒
☐
☐

REPAIRING WELL

☐
☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On Oct. 4, 1979, set bridge plug at 3552'. Spotted 110 gallons 15% acid across perforations at 2925-3549. Set packer at 3378'. Acidized perfs at 3416-3549 with 1,390 gallons acid using 18 ball sealers. Maximum pressure 4200 psi. and minimum was 1600 psi. at 3.3 BPM. Instant S.I. pressure was 1800 psi. Moved bridge plug to 3210'. Spotted 50 gallons acid across perfs at 3179-85. Set packer at 3133'. Acidized with 450 gallons. Pressure was 2600 to 1700 psi. Instant S.I. pressure - 1600 psi. Rate 3.5 BPM. Moved bridge plug to 3084'. Spotted 50 gallons acid across perfs. at 3026-57. Set packer at 3010'. Acidized with 950 gallons acid with 18 ball sealers. Communicated with perfs at 2925-34 when 1 barrel acid left in tubing. Pressure 3000 to 2300 psi. at 3.5 BPM. Instant S.I. pressure was 2200 psi. Pulled plugs and tubing. Ran new bridge plug to 3084'. Spotted 50 gallons acid across perfs at 2925-34. Set packer at 2885'. Acidized with 450 gallons at 2900 to 2300 psi. at 3.2 BPM.

RECEIVED

OCT 12 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

George H. Shaw

TITLE

Consulting Engineer

DATE Oct. 12, 1979

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.