



- ⊙ Wind Direction Indicators  
(wind sock or streamers)
- △ H2S Monitors  
(alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"  
RIG LAY OUT PLAT

HUDSON OIL COMPANY OF TEXAS  
WESCOTT FEDERAL # 1  
UNIT "M" SECTION 13  
T17S-R31E EDDY CO. NM