

Submit 3 Copies To Appropriate Districts

Office

District I

1625 N. French Drive., Hobbs, NM 88240

District II

811 S. First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State Of New Mexico
Energy, Minerals, and Natural Resources

Form C-103
Revised March 25, 1999

Handwritten initials: C15 F, JF

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Well API No.
30-015-02026

5. Indicate Type Of Lease
State Fee

6. State Oil and Gas Lease No.
B11595

7. Lease Name Or Unit Agreement
Name:
Gulf "A" State

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type Of Well:
Oil Well Gas Well Other

Name Of Operator
Ray Westall Operating

8. Well No.
001

Address Of Operator
P.O. Box 4 - Loco Hills, New Mexico 88255

9. Pool Name Or Wildcat
Artesia Qn Grayburg SA

Well Location
Unit Letter D : 660' Feet From The North Line And 660' Feet From The West Line
Section 23 Township 18S Range 28E NMPM County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, ect.)

11. Check The Appropriate Box To Indicate Nature Of Notice, Report Or Other Data

NOTICE OF INTENTION TO:
Remedial Work Plug And Abandon
Temporarily Abandon Change Plans
Pull Or Alter Casing Multiple Completion
Other

SUBSEQUENT REPORT OF:
Remedial Work Alter Casing
Commence Drilling OPNS. Plug and Abandonment
Casing Test and Cement Job
Other:

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/19/02 Rig up, found free point @ 500'
Spot 25 sxs (150') @ 2470'
Spot 25 sxs (150') @ 2100'
Spot 25 sxs (150') @ 1800' WOC - 1 hour
Spot 25 sxs (150') @ 800'
Tag 690'
Perforate squeeze holes @ 475'
Squeeze 50 sxs @ 325'
Wait On Cement - 1 hour
Tag @ 375'
Spot 7 sxs @ 375'
Perforate @ 60' - Pump 75 sxs
Circulate cement to surface

02/20/02 Install dry hole marker
Clean location

(Plugging approval and verbal changes by Van Barton NMOCDD-Artesia.)

Handwritten: Post PCH

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
Signature Rene Mathews Title Production Secretary Date 03/15/02

Type Or Print Name: Rene Mathews Telephone No. (505) 677-2370
(THIS SPACE FOR STATE USE)

APPROVED BY [Signature] Title Gulf Rep ID Date APR 4 2002
Conditions Of Approval If Any: