

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Minerals and Natural Resources Department


CLIF
OP

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
811 South First, Artesia, NM 88216

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410



OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-05460
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-3627
7. Lease Name or Unit Agreement Name Cedar Lake
8. Well No. 1
9. Pool name or Wildcat Grbg Jackson SR Q Grbg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3582'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation /
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>515</u> Feet From The <u>West</u> Line Section <u>30</u> Township <u>17S</u> Range <u>31E</u> NMPM <u>Eddy</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: _____ <input type="checkbox"/>
	PLUG AND ABANDON <input checked="" type="checkbox"/>
	CHANGE PLANS <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug as follows.

1. Set 100' cement plug 50' above and below bottom of 5 1/2 casing. WOC and tag (2877-2977)
2. Perforate 5 1/2 casing @ 1290' base of salt, squeeze 100' cement plug. WOC and tag (inside : outside cas.)
3. Perforate 5 1/2 casing @ 485' top of salt, squeeze 100' cement plug. WOC and tag. (inside : outside cas.)
4. Perforate 5 1/2 casing @ 60' and circulate to surface.
5. Install dry hole marker.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 3/8/02

TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO. 748-1288

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE MAR 13 2002

CONDITIONS OF APPROVAL, IF ANY: