

(May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT IN THE (Other Instructions on reverse side) CATE* on re-

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 01159

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FAF - Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Devonian Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 4-18S-30E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER []

2. NAME OF OPERATOR Franklin, Aston & Fair, Inc. ✓

3. ADDRESS OF OPERATOR P. O. Box 1090 Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FWL

RECEIVED DEC 6 1976 O.C.C. ARTESIA OFFICE

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3555' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF [] FULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON* [] REPAIR WELL [] CHANGE PLANS [] (Other) []

SUBSEQUENT REPORT OF:

WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT* [X] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12645

After completion through perforations 3546' to 3556' in the San Andres on December 14, 1974, production continued to decline until it was no longer economical to operate this well. The well was plugged and abandoned as follows:

Spotted 50 sacks cement plug at 3600' to 3500' and circulated heavy gel. The 9 5/8" casing was cut at 1086' and pulled. A 50 sack cement plug was spotted through tubing as follows:

50 sacks in and out of 9 5/8" casing at 1086' 50 sack plug at 550' at top of salt 10 sack plug and marker at surface

THIS APPROVED PER TELEPHONE CONVERSATION WITH MR. KNAUF 10-3-75

RECEIVED OCT - 6 1975 U.S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Geologist

DATE 10-3-75

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ADD [Handwritten notes]

*See Instructions on Reverse Side