

**NEW MEXICO OIL CONSERVATION COMMISSION**  
Santa Fe, New Mexico

**MISCELLANEOUS REPORTS ON WELL**

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Hobbs, New Mexico

11-7-39

Place

Date

OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico.  
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the  
**Me-Tex Supply Co.** State **16** Well No. **1** in the  
 Company or Operator  
**NW NW** of Sec. **16**, T. **18**, R. **31**, N. M. P. M.,  
**Shugart-Paton** Field, **Eddy** County

The dates of this work were as follows: \_\_\_\_\_

Notice of intention to do the work was (was not) submitted on Form C-102 on \_\_\_\_\_ 19\_\_\_\_\_  
 and approval of the proposed plan was (was not) obtained. (Cross out incorrect words.)

**DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED**

Well plugged with 30' caliche bridge from 3490' to 3520' - 30' cement plug from 3460' to 3490' - 50' caliche bridge 3100 to 3150' - 30' cement plug 3070 to 3100' - filled with mud to 1000' - 100' caliche bridge 900' to 1000' - 50' cement plug 850' to 900' - 8 5/8" OD pipe knocked off at 570' and pulled, hole filled to top with mud and marker cemented over same.

Witnessed by \_\_\_\_\_  
 Name Company Title

Subscribed and sworn to before me this \_\_\_\_\_  
**15** day of **November**, 19 **39**  
**SEAL**  
**Don Hudgens**  
 Notary Public

I hereby swear or affirm that the information given above is true and correct.  
 Name **B. W. Jarboe**  
 Position **Prod. Supt**  
 Representing **Me-Tex Supply Co.**  
 Company or Operator  
 Address **Hobbs, New Mexico**

My Commission expires **October 15, 1941**

Remarks:

**Roy Yarbrough**  
 Name  
**Oil & Gas Inspector**  
 Title

THE UNIVERSITY OF CHICAGO

DEPARTMENT OF CHEMISTRY

PHYSICAL CHEMISTRY

LECTURE NOTES

BY

PROFESSOR

OF CHEMISTRY

AND

PHYSICS

OF THE UNIVERSITY OF CHICAGO

CHICAGO, ILLINOIS

1954

BY

PROFESSOR

OF CHEMISTRY

AND

PHYSICS

OF THE UNIVERSITY OF CHICAGO

CHICAGO, ILLINOIS

1954

BY

PROFESSOR

OF CHEMISTRY

AND

PHYSICS

OF THE UNIVERSITY OF CHICAGO

CHICAGO, ILLINOIS

1954

BY

PROFESSOR

OF CHEMISTRY

AND

PHYSICS

OF THE UNIVERSITY OF CHICAGO

CHICAGO, ILLINOIS

1954

BY

PROFESSOR

OF CHEMISTRY

AND

PHYSICS

OF THE UNIVERSITY OF CHICAGO

CHICAGO, ILLINOIS

1954