## Submit 3 Copies to Appropriate District Office

## State of New Mexico erals and Natural Resources Department

Form	C-103	
Revis	ed 1-1-8	9

DISTRICT			
D.O. Por 1090	**	A TR #	00240
DO DOS IGMI	HANNE	NM	AA / 41.

OIL CONSERVATION DIVISION P.O. Box 2088

Santa Fe. New Mexico 87504-2088

WELL API NO.

		3	<u> 30-</u>	0	15	-28424
-	-	 	· · · · ·	_		

P.O. Drawer DD, Artesia, NM 88210	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG-864
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	TO A  7. Lease Name or Unit Agreement Name
1. Type of Well: OR. GAS WELL X WELL OTHER	Amole AMM State Com
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 2
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat Dagger Draw Upper Penn, North
4 Well Location	1980 Feet From The West Line
Section 16 Township 19S Range 25E	NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	tice, Report, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
TEMPONANILI ABANDON	ORILLING OPNS.  PLUG AND ABANDONMENT L
PULL ON ALTER CASING	AND CEMENT JOB
OTHER:	oduction casing & cement X
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dework) SEE RULE 1103.  TD 8320'. Reached TD at 4:15 AM 6-3-95. Ran 203 joints of 7" 26# N-80 sandblasted (741.86'); 4 joints of 7" 26# J-55 varnished (2511.87'); 91 joints of 7" 26# J-55 varnished (972.60 varnished (210.46') (Total 8321.74') of casing set a Float collar set at 8278'. DV tool set at 6040'. CS stage 1: 500 sacks Super C, 2/10% CF-2, 3/10% CF-14. (yield 1.76, weight 13.0). PD 4:50 PM 6-4-95. Bumph Circulated 157 sacks. Circulated through DV tool for Pacesetter Lite C, 5#/sack gilsonite, 5#/sack salt a weight 12.4). Tailed in with 100 sacks Class H Neat PM 6-4-95. Bumped plug to 3300 psi for 1 minute. Cat 2:30 AM 6-5-95. Waiting on completion unit.	ints of 7" 26# & 23# casing as follows: ints of 7" 26# J-55 sandblasted (146.63') ints of 7" 23# J-55 varnished 68') and 5 joints of 7" 26# N-80 t 8320'. Float shoe set at 8320'. emented in two stages as follows: A, 3.42# sark salt and 8#/sack hiseal ed plug to 1900 psi for 1 minute. r 3-1/4 hours. Stage 2: 900 sacks nd 1/4#/sack celloseal (yield 2.01, (yield 1-18, weight 15.6). PD 10:30
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	( 5 05
	tion Clerk DATE 6-5-95
TYPEOR PRINT NAME Rusty Klein	TELEPHONE NO. 505/748-1471
(This space for State UORIG) #4L SIGNED BY TIM W. GUM	JUN 7 1995

TITLE -