

CLSF

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO NM01119
2. NAME OF OPERATOR Bill Taylor		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 1106 N. Country Club, Carlsbad, NM 88220		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FSL & 2310' FEL		8. FARM OR LEASE NAME Welch Federal
14. PERMIT NO.		9. WELL NO. Riggs #1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3290' GL		10. FIELD AND POOL, OR WILDCAT Cedar Hills Yates
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 5-T21S-R27E, NMPM
		12. COUNTY OR PARISH EDDY
		13. STATE NM

RECEIVED
OCT 1992
O. C. D.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Plugging Actions</u> <input checked="" type="checkbox"/>	
(Other)		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Oct. 26, 1992: Placed 35 sacks Type I & II Cement through 540' of 2 3/8" tubing; witnessed by BLM personnel.

Oct. 27, 1992: Tagged top of cement at 203'; witnessed by BLM personnel; circulated loose material from hole.

Oct. 28, 1992: 5 1/2" and 7" casings preforated by Black Warrior, four shots at 185'.

Oct. 29, 1992: Ran tubing to 198' and placed 25 sacks Type I/II cement, as instructed by BLM.

Oct. 30, 1992: Tagged top of cement at 184'-11"; witnessed by BLM personnel. Placed 25 sacks cement through tubing at 184' as instructed by BLM, with 5 lbs. flocele.

Nov. 2, 1992: Tagged top of cement at 43', witnessed by BLM personnel.

Nov. 4, 1992: Placed 9 sacks cement through 42' of tubing; circulated 3 sacks. SET REGULATION MARKER AT SURFACE.

Part ID-2
12-4-92
P4A

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Bill Taylor</u>	TITLE <u>Operator</u>	DATE <u>11/4/92</u>
(This space for Federal or State office use)		
APPROVED BY _____	TITLE _____	DATE <u>11/18/92</u>
CONDITIONS OF APPROVAL, IF ANY:		

*See Instructions on Reverse Side