

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED BY
JAN 16 1985
P.O. BOX 2088
SANTA FE, NEW MEXICO 87501

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Harvey E. Yates Company

3. Address of Operator
P. O. Box 1933, Roswell, New Mexico 88201

4. Location of Well
UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM
The West LINE, SECTION 18 TOWNSHIP 20S RANGE 27E NNPM.

7. Unit Agreement Name

8. Farm or Lease Name
Hondo Singer "C"

9. Well No.
1

10. Field and Pool, or Wildcat
WIC Bone Springs

11. Elevation (Show whether DF, RT, GR, etc.)
3331' GR

12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1/09/85 MI to P & A well.

1/10/85 Tag retainer @ 6731'. Pump 10 sxs (35') cmt on top of retainer. GIH to 6505' pump 35 sxs (125') cmt over perms @ 6463 - 6505'.

1/11/85 GIH & tag plug over perms @ 6387' & spot 100' plug (25 sxs) from 5350' to 5250'. Spot 100' plug (25 sxs) from 4000' to 3900'.. Spot 200' plug @ 2983' (55 sxs). Pull 2 3/8" to 1600' close rams. Pump 30 sxs through hole in 7" csg @ 2930'.

1/12/85 Spot 30 sxs cmt w/2% CaCl @ 2920'. Pull tbq to 392' & spot 25 sxs cmt. Pull to 125' & spot surface plug.

1/13/85 Remove tbq head & cut 7", remove slips & ND 7" csg spool. Install Dry Hole Marker. Well P & A completed 1/12/85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray L. Doherty TITLE Reservoir Eng. DATE 1/15/85

Original Filed by
MRS. VANDERBILT

APPROVED BY _____ TITLE _____ DATE DEC 9 1986

CONDITIONS OF APPROVAL, IF ANY.