

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Corp. DIV-4001.2
1301 W. Grand Avenue

Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM 53219

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Nearburg Producing Company

3. Address and Telephone No.

3300 North "A" Street, Bldg 2, Ste 120, Midland, TX 79705 (915) 686-8235

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit, 780' FNL and 1350' FEL, Section 11-T22S-R24E

8. Well Name and No.

Chama Federal Com #1

9. API Well No.

30-015-24953

10. Field and Pool, or Exploratory Area

Indian Basin Upper Penn Associated

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Nearburg Producing Company request to plug and abandon the above referenced well.

1. TIH w/ tbg, load hole w/ mud.
2. Spot 100' f/ 7600' to 7500'. (25 sx) (Top of Wolfcamp 7580')
3. Spot 100' f/ 5100' to 5000'. (25 sx)
4. Cut csg @ 4000' and pull.
5. Spot stub plug 50' in and 50' out. (35 sx) (Tag)
6. Spot 100' plug f/ 3100' to 3000'. (35 sx) (Top of Bone Spring 3114')
7. Spot 100' plug f/ 1460' to 1430'. 1360' - 1460'
8. Spot 100' plug f/ 700' to 600'.
9. Set 50' surface plug & install dry hole marker.

50'

10. CFBP @ ±10,200' w/ 25 SX ON TOP



14. I hereby certify that the foregoing is true and correct

Signed *Kim Stewart*

(This space for Federal or State office use)

Title Regulatory Analyst

Date 06/14/2002

Approved by
Conditions of approval, if any:

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED

2002 JUN 17 AM 9:41

BUREAU OF MOUNT
ROSWELL OFFICE